

ASS. REQ. BY:

REF: TV 1Kernoch

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OO / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/v: _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

10:30am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$89k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMP 407YYr Regn: 09, 19Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ToyAltisC.O. 1598Colour: M. Black

AC: Insured / Std / NI / NA

Sp. Reading: 337245

T/Radio: Insured / Std / NI / NA

Eng No: _____

C No: NR053REH604599197Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt or

Mod: Nil / B/Rim / STD A/Rim or

Tyre Size: P: _____

215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 1/6/24D.O.I. 11/6/2024

Survey held at _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

o/s rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

) S - RS. SI

) Parking

) Others

Report Format :

Lump Sum / I.B.I. (\$ _____)

TOTAL

City Auto Pte Ltd (Co. Reg No. 199503435C)
 160 Sin Ming Drive #05-01, Sin Ming AutoCity,
 Singapore 575722
 Tel: 6453 1235 Fax: 6453 7944 Email: jason@cityauto.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	01/06/2024
Vehicle Reg. No.:	SMP407Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	Koh Choon Mong		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 Elegance (A)	Vehicle Reg. Date:	06/09/2019
Vehicle Colour:	Black		
Engine No:	1ZR0E13112V	Chassis No:	MR053REH604599197
Odometer:	0 KM		

NOT Notified

1/1 Sep 8

Repair After Party

Paint Type:	
List Item Discount:	25.00 %
Total Loss?	NO
Est. Duration of Repair (day):	<i>4 days</i>

Present Location: **CITY AUTO PTE LTD (HQ)**

COST OF CLAIMS		Amount
		5,478.22
Parts		237.00
Miscellaneous Items		1,480.00
Labour		0.00
Paintwork Labour		0.00
Towing		
Gross Total (S\$)		7,195.22
+ GST 9.00% (S\$)		647.57
Nett Amount (S\$)		7,842.79

This claim is handled by: VRONICA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2024)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 Elegance (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: City Auto Pte Ltd/SMP407Y/08/06/2024 09:20	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Rear RH door	25.00	0.00	1,864.60 FL	X
2	1		*Rear RH fender	25.00	0.00	1,715.00 FL	X
3	1		*Rear RH wheel rim	25.00	0.00	2,731.50 FL	X
4	1		*Rear bumper	25.00	0.00	*828.80 FL	X
5	1		*Rear bumper retainer RH	25.00	0.00	*164.40 FL	X

F=Franchise part L=ListItemDisc

Sub Total (\$\$) 7,304.30
 - List Item Discount on L Items (\$\$) 1,826.08

Total Parts (\$\$) 5,478.22

City Auto Pte Ltd/SMP407Y/08/06/2024 09:20. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Rear RH wheel tire	Sm 225.00 X
2	1	OD/TP Case (Insurer)	12.00
Sub Total (S\$)			237.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts.	New	600.00 400/
2	Spray painting on affected and replace parts.	New	800.00 600/
3	Computerized wheel alignment.	New	nn 80.00 X
Gross Labour Cost (S\$)			1,480.00

City Auto Pte Ltd/SMP407Y/08/06/2024 09:20. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >