

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN		Ref:	CS/INC24070189/Anh3m4	
	75 BRAS BASAH RO	DAD SINGAPORE 189557	Date:	24/10/2024	
	WOOME GENTRE	5.11.67.11 GTC 100007	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 2289X	Veh. Inspected	SLA 8171P	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1284871-002	Excess	\$0.00	
	Assign From	JULIE MANGUBAT	Assign Date	10/07/2024	
2. Vehicle Details					
	Make & Model	HONDA VEZEL	C.C	1496	
	Engine No.	L15B4029545	Year of Reg.	17/03/2016	
	Chassis No.	RU11109542	Colour	YELLOW	
	Odometer	504299 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60R16	TOURADOR	6	
	L/H Front Tyre	215/60R16	TOURADOR	6	
	R/H Rear Tyre	215/60R16	TOURADOR	6	
	L/H Rear Tyre	215/60R16	TOURADOR	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	. General Information				
	Accident Date	04/07/2024	Inspection Date	10/07/2024 (11:43)	
	Survey held at	ONE GARAGE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair			

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days