

(08/11/13) . wef

ASS. REC. BY: Marius

REF:

CS/GA124070187/4vh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspection Vehicle No: FBN5529L

at Workshop m/s SMH

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: £7k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C2881c

Vehicle: IN / OUT

Date: _____ Person Contacted: L7A 1691

Veh No: FBN5529L Yr Regn: 24/10/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Nmax 155 c.c. 155

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 124837 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH356431 000008517

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70-13

R: 130/70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or maxxis

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 01/07/24 D.O.I. 11/07/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 20/1600

never fall
2/5 \$300

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	288K
Vehicle Details	
Vehicle No.:	FBN5529L
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jul 2024
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX155 ABS
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	G3H6E0011000
Chassis No.:	MH3SG431000008517
Maximum Power Output:	-
Open Market Value:	\$2,511.00
Original Registration Date:	24 Oct 2018
First Registration Date:	24 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$377.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,951.00
COE Rebate Amount:	\$1,691.00
Total Rebate Amount:	\$1,691.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 11 Jul 2024

OK



Contact Us for Details

Open

Bike model

Type Of Vehicle

Any

Price From

Any

Price To

Any

Class

Any

Search

More Search Options

Sort By

Sort By

Recommended

Yamaha Nmax 155

Reg Date : 30/03/2022

Vehicle Type : Scooters

Capacity : 155cc

Mileage : 40563km

Posted on : 25/06/2024

SGD \$11800

★ Paid Ad

★ Dealer Ad

Details >

Yamaha Nmax 155

Reg Date : 14/12/2018

Vehicle Type : Scooters

Capacity : 155cc

Mileage : 79643km

Posted on : 28/05/2024

SGD \$7900

★ Paid Ad

★ Dealer Ad

Details >

Yamaha Nmax 155

Reg Date : 09/05/2019

Vehicle Type : Scooters

Capacity : 155cc

Mileage : 95774km

Posted on : 11/06/2024

SGD \$8800

★ Paid Ad

★ Dealer Ad

Details >



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 47029

Customer :

GREAT AMERICAN INSURANCE COMPANY, SINGAPORE BRANCH
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

DATE : 10/07/2024
CLAIM NO. : 12534
POLICY NO. : MC/01009082/02
FROM : RAYMOND

VEHICLE NO. : FBN5529L
MAKE/MODEL : YAM / NMAX155 ABS

*not authorized
for
now
11/7/24
2 days
telephone advice*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766	Supply/Install	2.00	\$85.00	170.00
2	LAMP TAIL ASSY P/N: 60928 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$254.00	254.00
3	MUDGUARD REAR P/N: 60932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$57.00	57.00
4	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
5	TRANSPORT CHARGES P/N: 07169		1.00	\$62.00	62.00

SUB TOTAL

GST @ 9 %

GRAND TOTAL (SGD)

\$574.00

\$51.66

\$625.66

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

*P-342
102
307.60
100
407.60
202
326*

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts for resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*47029 *



bizSAFE₃



Sl	Description	Qty	Unit Price	Amount
----	-------------	-----	------------	--------

This quotation is sent via email / WhatsApp with our computer-generated signature.

*47029 *



bizSAFE

