

# ASSIGNMENT

Front: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin: \_\_\_\_\_  
 OD / TP RES / OD RES / EVA / INV / MV  
 To in Vehicle No: \_\_\_\_\_  
 at VO \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repair: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: YN 7973B Yr Regn: 2015, April  
 Type: M.Car / M.Cycle / Bus / Van / Com / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Hino XZU710R C.D. 4009  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: 220987 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JHHU CS3H60 K011804  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 7.00R16  
 R: 7.00R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 12/07/24

Survey held at Automobile Hub.

Des. of Damages: Frt / Rear / D/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                   |
|-------------|----------------------------------------|
|             | <u>TP Sampo</u>                        |
|             | <u>COE Expiry</u>                      |
|             | <u>Estimate given during : Yes (✓)</u> |
|             | <u>1st Survey : No (✓)</u>             |
|             | <u>MV : 17K</u>                        |
|             | <u>PV : 3K</u>                         |
|             | <u>Nett. 14K</u>                       |
|             | <u>403H.</u>                           |

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + R.S. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

Report Format: \_\_\_\_\_

Report Format: \_\_\_\_\_