



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|-----------------|--|-----------------|------------------------|
| MS SOMPO INSURANCE SINGAPORE PL | | Ref: | | CS3/SMO24070199/Uvp3e2 |
| 50 RAFFLES PLACE #03-03 | | Date: | | 18/07/2024 |
| SINGAPORE LAND TOWER SINGAPORE 048623 | | Code: | | SMO |
| 1. Policy Particulars :- PRE-REPAIR SURVEY | | | | |
| | Insured Veh. | SJC 5986M | Veh. Inspected | SDY 3280J |
| | Policy No. | - | Coverage | 0 |
| | Claim No. | CMTD2402265/THE | Excess | \$0.00 |
| | Assign From | IRENE HENRY | Assign Date | 11/07/2024 |
| 2. Vehicle Details | | | | |
| | Make & Model | MAZDA 3 (A) | C.C | 1496 |
| | Engine No. | P520336856 | Year of Reg. | 29/01/2016 |
| | Chassis No. | JM6BM42A8G0328231 | Colour | WHITE |
| | Odometer | 312077 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | General | GOOD |
| | Modification(s) | RIMS: SPORTS RIM | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance (mm) |
| | R/H Front Tyre | 205/60R16 | FALKEN | 5 |
| | L/H Front Tyre | 205/60R16 | FALKEN | 5 |
| | R/H Rear Tyre | 205/60R16 | FALKEN | 5 |
| | L/H Rear Tyre | 205/60R16 | FALKEN | 5 |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. | | | | |
| 5. General Information | | | | |
| | Accident Date | 08/07/2024 | Inspection Date | 15/07/2024 (11:08AM) |
| | Survey held at | 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY - TSA TRANSPORT | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800-\$2,500 | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | |

CKS

MARCUS CHUA KANG SENG
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.