

REF: CS/LIP24070212/Avh3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estim: ~~Estim~~OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MVTo In ~~Vehicle~~ No: \_\_\_\_\_at ~~W/O~~ ~~Estim~~ / m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: **GBG 9709U**

Policy No: \_\_\_\_\_

Claim's No: **AVS24/2142**

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repair: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **FBT1810T**Yr Regn: **2021 Nov**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Yamaha****Nmax**

c.s

**155**Colour: **Silver**

A/C: Insured / Std / NI / NA

Sp. Reading: **107800**

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **MH3S63680 MK104090**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: **120/70 R13**R: **130/70 R13**BS / DUN / EXNOVA / GY / FS / IZA / MIG / DHTSU / ☒ PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. **06** mmR/Bal. **06** mm

L/Bal. mm

L/Bal. mm

D.O.A. **29/6/2024**D.O.A. **11/07/24**Survey held at **JEC**Des. of Damages: Frt / Rear / ☒ S / ☒ W / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

**TPLiberty**

26/9/24 Adrian confirmed LS \$2000 (Red 4691.70, 70%)

1/10/24 Adrian re-confirmed LS \$1900 (Red 4791.70, 71%)

MV: **121K**PV: **6.6K**Nett: **5.4K**COE Expiry: **1**

Estimate given during: Yes ( )

1st Survey: No (✓)

**533C**

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: **3**

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Inve (\$)

Survey Fee:

Transportation:

3 + R.S. \$1

Photos

Others

Report Format: \_\_\_\_\_

Report Form: \_\_\_\_\_