



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070214/Kqp3e2
(BUDGET DIRECT INSURANCE)	Date:	11/07/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMR 5265X	Veh. Inspected	SMG 9854C
Policy No.	-	Coverage	0
Claim No.	C10030487/JK	Excess	\$0.00
Assign From	MICHAEL	Assign Date	11/07/2024

2. Vehicle Details

Make & Model	KIA CERATO (A)	C.C	1591
Engine No.	G4FGJH713211	Year of Reg.	08/01/2019
Chassis No.	KNAF1416MK5024522	Colour	METALLIC DARK BLUE
Odometer	158336 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45R17	FARROAD	8
L/H Front Tyre	225/45R17	FARROAD	8
R/H Rear Tyre	225/45R17	GLENLANDER	8
L/H Rear Tyre	225/45R17	GLENLANDER	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/07/2024	Inspection Date	15/07/2024
Survey held at	EM SOLUTION PTE LTD - 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days