

ASSIGNMENT

Front: _____ Date: _____
 Est: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To In _____ Vehicle No: _____
 at VVO _____
 of _____
 Insured: _____
 Policy: _____
 Claims: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKQ6090E Yr Regn: 2014, Dec

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish C.D. 1798

Colour: Gold A/C: Insured / Std / NI / NA

Sp. Reading: 176811 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDG620W90J001846

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15
R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 09/07/24

Survey held at J-Mart

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG

COE Expiry: _____

Estimate given during: Yes ☒
1st Survey: No ☒

MV: 2.1K

PV: 12.9K

Nett: 8.1K

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Inve (\$)

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Form: _____

Report Form: _____

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration NO: 201400246D
GST Reg. NO: 201400246D

9-Jul-24

Our ref : TP/5431/24

Teo Kay Chwee

RE : Estimate cost for vehicle no : SKQ 6090E

1 pc	rear bumper	<i>Del d</i>	\$	671.80	<i>✓</i>
1 pc	rear bumper rh retainer	<i>sea</i>		65.00	<i>+</i>
4 pcs	rear bumper clips	<i>ru</i>		20.00	<i>✓</i>
1 pc	rear rh door chrome	<i>cut</i>		125.00	<i>+</i>
1 pc	rh rocker garnish	<i>Rgs</i>		568.00	
				1,449.80	
				less 25%	
				362.45	
				1,087.35	
1 pc	rear rh tyre	<i>cut</i>	snett	400.00	<i>-160</i>
1 pc	rear rh rim	<i>cut</i>		400.00	<i>-300</i>
				600.00	<i>-300</i>
				1,000.00	<i>-800</i>
				3,487.35	
				Plus 9% GST	
				313.86	
				3,801.21	

SD : Three thousand eight hundred one & cents twenty-one only.

Adnan Lj
2/s 08/07/24
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: