

DS/LPC24060055/Epa3q2

ASSIGNMENT

Veh No: **SLL4040C** Yr Regn: **19 Dec 2018**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MAZDA 3 C.C 1496

Colour **White** A/C: Insured / Std / NI / NA

Sp. Reading 65395 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8K0265147 *

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

N/S	O/S
xxx	

Tyre Size: F: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Front Rear

R/Bal.	7	mm	R/Bal.	7	mm
--------	---	----	--------	---	----

L/Bal.	7	mm	L/Bal.	7	mm
--------	---	----	--------	---	----

D.O.A. 08/06/24 D.O.I. 20/06/24

Survey held at **TRANS EUROKARS**

Survey held at **TRANS EUROKARS**

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐: Preli. Report

□ : Final Report

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$

Tech. Invs (\$)

☐ Weekend (\$

$$S + RS \rightarrow SI$$

Photos

	Others
--	--------

TOTAL

Report Format :

LEWIS & CLARK / 1804-05