

(08/11/13) We:

REF:

CS/105 24070236/4023

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: F3554884at Workshop m/s BHM

of _____

Insured: SLL 9149R

Policy No. _____


Claims No. DMPC2400842H/ST

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 11800

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 1426Date: _____ Person Contacted: LTA 55486

Vehicle: IN / OUT

Veh No: F3554884 Yr Regn: 25/05/24Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Niro c.c. 155Colour: white A/C: Insured / Std / NI / NASp. Reading: 46714 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH356560MK074543Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or offBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110-70-13R: 130-70-13BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 05/07/24 D.O.I. 15/7/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt, n/s, o/s Body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 02/1006k? NOK & 6314TOTAL LOSS? 16500 including straighten body alignment.9/10/24 d/s & 4750 informed Raymond (red 3957, 45%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	142G
Vehicle Details	
Vehicle No.:	FBS5488U
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2024
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX 155 ABS CVT
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	G3L8E0522891
Chassis No.:	MH3SG5680MK074543
Maximum Power Output:	-
Open Market Value:	\$2,737.00
Original Registration Date:	25 May 2021
First Registration Date:	25 May 2021
Transfer Count:	3
Actual ARF Paid:	\$411.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2031
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$8,000.00
COE Rebate Amount:	\$5,486.00
Total Rebate Amount:	\$5,486.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 15 Jul 2024

OK


Vehicle Details

Vehicle No.	Make / Model
FBS5488U	YAMAHA / NMAX 155 ABS CVT
Vehicle Type :	Vehicle Attachment 1 :
P00 - Passenger Motorcycle/Autocycle /Moped	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	MH3SG5680MK074543
Propellant :	Engine No. :
Petrol	G3L8E0522891
Motor No. :	Engine Capacity :
-	155 cc
Power Rating :	Maximum Power Output :
-	-
Maximum Laden Weight :	Unladen Weight :
287 kg	132 kg
Year Of Manufacture :	Original Registration Date :
2021	25 May 2021
Lifespan Expiry Date :	COE Category :
-	D - Motorcycle
Quota Premium :	COE Expiry Date :
\$8,000.00	24 May 2031
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
24 May 2025	-
Inspection Due Date :	Intended Transfer Date :
24 May 2025	12 Jul 2024
CO2 Emission :	CEV/VES Rebate Utilised Amount :
-	-

Motorcycles

356 search results for 'YAMAHA NMAX 155 2021' in Singapore

Save this search ☐ ⚙️



YAMAHA NMAX 155 2021

in: Motorcycles ×

All of Singapore

Search

Motorcycles ▾

Sort: Best Match ▾

Body ▾


Make ▾

Condition ▾


Price ▾

Deal Option ▾


More filters ⚙️




YAMAHA NMAX 155 V2 2021 \$240 monthly for 48 month
S\$10,300
♡ 325




YAMAHA NMAX 155 ABS COE MAY 2031
S\$11,888
♡ 15




YAMAHA NMAX 155 V2 COE TILL 05/2031
S\$11,888
♡ 13





Yamaha Nmax 155 2021
S\$13,800
♡ 30

 mottomoto
3 hours ago





Yamaha Nmax 155
S\$11,888
♡ 1

 romeo_seah
5 hours ago





Yamaha Nmax 155 sale direct owner
S\$14,500
♡ 1

 revologybikes
15 minutes ago





YAMAHA 155 SERIES - SNIPER T155 | EXCITER155 | MXKING150 ...
S\$1,000 ~~S\$2,000~~
♡ 14


 powermotor
56 minutes ago





YAMAHA NMAX 155 | NMAX V2 | NMAX 155 V2 | NMAX155 | ...
S\$12,888
♡ 130


 revology
1 hour ago





 vincent2503
1 hour ago




 revologybikes
1 hour ago



 pioneerautocredit
2 hours ago



Motorcycles > Motorcycles for Sale > Class 2B > Yamaha



Yamaha Nmax 155

S\$11,888

Used

Meetup

MV Augusta



S\$11,888 Used Meetup MV Augusta

3 hours ago

Yamaha

SCOOTER

Pre owned Yamaha Nmax 155 V2 for sale!

Bone stock bike, with decent engine condition!

Brand new coverset to go with!

COE until 17/06/2031

[read more](#)

Meet-up

MV Augusta

Meet the seller



Motto Moto

@mottomoto

Joined 3 years ago

Very Responsive

Verified

Reviews for @mottomoto 5.0 ★★★★★ (171)



@ahmad.alqadri86 · 10 days ago

★★★★★

Danial from the bike shop is what every salesperson should be. Very knowledgeable and took time to explain to me the different bikes they had and which



Motto Moto @mottomoto

5.0 ★★★★★ (171 reviews)

Chat

Sign in to make offer

1 like

Chat

Returns and refunds

Depends on the seller's decision. Not covered by Buyer Protection.

Safety policy

Pay only at the meet-up. Transferring money directly to strangers puts you at risk of e-commerce scams.

Advertisement

SB0F24780001 / Ban Hock Hin Co Pte Ltd
ENTRY DATE & TIME: 08/07/2024 16:46 (SGT)
SUBMITTED BY: Tan Chok Lok
VERSION: 1 (08/07/2024 16:46 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	08/07/2024 16:46 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	05/07/2024 13:00 (SGT)
Exact Location of Accident	51 Hougang St 51, Singapore 530567
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBS5488U
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MOHAMAD IRSYAD BIN MOHAMAD HISAM
NRIC No	TXXXX142G
Email Address	mohdirsyad1423@gmail.com
Mobile Phone No	(Phone) +65-97809065
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Yamaha
Model	NMAX 155
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Auto
CC	155

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	A300835304VMP

DRIVER

Name of Driver	MOHAMAD IRSYAD BIN MOHAMAD HISAM
NRIC No	TXXXX142G

Driving Pass Date	04/01/2022
Driving experience	2 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97809065
Alt. Phone Number	-
Email Address	mohdirsyad1423@gmail.com
Address	BLK 577 HOUGANG AVENUE 4
Address complement	#05-660
Postcode	530577
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head on collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Hougang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18004890999
Alt. Police Station Phone No	(Fax) +65-63128989
Police Station Address	60 Hougang Ave 9 Singapore 538775
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE TRAFFIC ACCIDENT REPORT NO. T/20240706/2066 ATTCHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL9149R
Vehicle Manufacturer	Honda
Vehicle Model	-

Vehicle Colour	White
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-90670129
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	MOHAMAD IRSYAD BIN MOHAMAD HISAM
Gender	Male
Phone No	(Phone) +65-97809065
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	FBS5488U
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	Yes

WITNESS DETAILS

WITNESS 1

Name	LATIF
Phone	(Phone) +65-81212432
Email	-

WITNESS 2

Name	SYUKRI
Phone	(Phone) +65-98242631
Email	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan




Describe Circumstance of the Accident


refer to Report No. T | ~~2040~~ 20240706 | 2066

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

**SINGAPORE
POLICE FORCE**

T/20240706/2066

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3

Report No. T/20240706/2066

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/07/2024 18:48		Vide Report No.:		Station Diary No.: 94	
Informant's Particulars					
Name of Informant: MOHAMAD IRSYAD BIN MOHAMAD HISAM			Address: APT BLK 577 HOUGANG AVENUE 4 #05-660 SINGAPORE 530577		
ID Type / ID No.: NRIC NO / T0121142G			Contact No.: Home/Office: Mobile: 97809065		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 22	Date of Birth: 14/07/2001	Type of Informant: Rider		
Race: Javanese			Language:		
Occupation: FOOD DELIVERY RIDER			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 05/07/2024 13:00	Type of Location: Straight Road
Location: HOUGANG STREET 51				
Weather: Clear		Road Surface: Dry		
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Conditio	No of Passenger
FBS5488U	Motorcycle				Seriously Damaged	0
SLL9149R	Motor car				Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

**SINGAPORE
POLICE FORCE**

T/20240706/2066

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3
Report No. T/20240706/2066

CONTINUATION OF REPORT

Rider			
Name	MOHAMAD IRSYAD BIN MOHAMAD HISAM	ID No.	T0121142G
Related Vehicle	FBS5488U (Motorcycle)	Contact No.	97809065
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry	Class: 2B Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of	Slight

Brief Details.

On 05/07/2024 at about 1300 hours, I was riding my motorcycle (FBS5488U) along Hougang St 51 towards Buangkok Green when another vehicle (SLL9149R) suddenly came out from the Hougang Green Shopping Mall carpark and I was unable to stop in time, thus, colliding into said vehicle. I lost consciousness for a while and when I regained conscious, the nearby members of public assisted me to the roadside. Paramedics and police were called down to scene. I was attended by the paramedics and eventually convey to Sengkang General Hospital. I received five days of medical leave to recover from my injuries. I did not manage to speak with the police at scene and am unsure of the incident number. I recalled I was riding at an approximate speed of 30KM/H to 40km/h.

There were people at the scene who witnessed the accident and provided their name and contact number:

- Latif (HP: 8121 2432)
- Syukri (HP: 9824 2631)



SINGAPORE
POLICE FORCE



T/20240706/2066

3 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20240706/2066

CONTINUATION OF REPORT

Signature of Officer Recording The
F/
SGT 2 IMAN SYAHIRAN BIN
SALEHUDIN

A handwritten signature in black ink, appearing to be "Iman", with a small flourish at the end.

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
SR STAFF SGT Ahmad Syafiq Bin Harris
Contact No.: 65476201

Signature Of Informant:

A handwritten signature in black ink, appearing to be "hy", with a small flourish at the end.

Date/Time:
06/07/2024 18:48

Classification Of Case:



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 47048

Customer :

ECICS LIMITED
T TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
Singapore 038987

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBS5488U
MAKE/MODEL : YAM / NMAX155 ABS

DATE : 11/07/2024
CLAIM NO. : 12537
POLICY NO. : A300835304-VMP

FROM : RAYMOND

*not follow
his
repairs
15/7/24
1/5 #4750
invald rep-
5 days
the ph. the mpr*

(Page 1 of 6)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE FRONT WHEEL P/N: 59126 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	<i>Surf</i> 19.00
2	BAR HANDLE P/N: 77867 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	<i>Surf</i> 68.00
3	BEARING 6300-2NS (NACHI) P/N: 38347 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$16.00	<i>Surf</i> 32.00
4	BELLY PAN P/N: 73891 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	<i>Surf</i> 37.00
5	BOARD FOOTREST LH P/N: 73893 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	<i>Surf</i> 37.00
6	BOARD FOOTREST RH P/N: 73890 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	<i>Surf</i> 37.00
7	BODY ALIGMENT	Repair	1.00	\$775.00	<i>Surf</i> 775.00
8	BOLT MUDGUARD P/N: 72316 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$13.00	<i>Surf</i> 52.00
9	BOLT, FLANGE DEEP RECESS - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	<i>Surf</i> 10.00
10	BRAKE DISK FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	<i>Surf</i> 78.00

*47048 *




bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
11	CALIPER ASSY (RIGHT) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$109.00	<i>Dange</i> 109.00 ✓
12	CARPET PAPAN ALLOY FOOTBOARD (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	<i>Dange</i> 85.00 ✓
13	CAST WHEEL, FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$249.00	<i>wey</i> 249.00 ✓
14	CLAMP P/N: 71186 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	<i>ner</i> 6.00 ✓
15	CLAMP - (REPORTED BY MECHANIC)	REPLACE	7.00	\$5.00	<i>ner</i> 35.00 ✓
16	CLIP NUT SPRING P/N: 59586 - (REPORTED BY MECHANIC)	REPLACE	10.00	\$2.00	<i>ner</i> 20.00 ✓
17	COVER CARBON FIBER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$651.00	<i>Cny</i> 651.00 ✓
18	COVER SET P/N: 80928 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$496.00	<i>Cny</i> 496.00 ✓
19	COVER, METER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	<i>ner</i> 28.00 ✓
20	DAMPER PLATE (1) P/N: 83665 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	<i>ner</i> 12.00 ✓
21	DAMPER, PLATE (2) - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	<i>ner</i> 10.00 ✓
22	DAMPER, PLATE (3) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	<i>ner</i> 8.00 ✓
23	DAMPER, PLATE (4) - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	<i>ner</i> 10.00 ✓
24	EMBLEM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	<i>ner</i> 5.00 ✓
25	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$16.00	<i>ner</i> 32.00 ✓

*47048 *

2091



S/N	Description	Action	Qty	Unit Price	Amount
26	EMBLEM 3D P/N: 79528 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$47.00	<i>mer</i> 94.00
27	EMBLEM ABS P/N: 81023 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	<i>mer</i> 16.00
28	EMBLEM PANEL FRONT P/N: 64172 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	<i>mer</i> 10.00
29	FENDER INNER P/N: 77862 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	<i>mer</i> 37.00
30	FORK FRONT ASSY LH&RH P/N: 77863 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$485.00	<i>sup/mer</i> 485.00
31	FRONT FLASHER LIGHT ASSY 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	<i>cm</i> 27.00
32	GRAPHIC 1 P/N: 79519 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	<i>mer</i> 12.00
33	HEADLAMP ASSY P/N: 74724 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$411.00	<i>sup</i> 411.00
34	HOLDER, BRAKE HOSE 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	<i>twi</i> 8.00
35	HOLDER, BRAKE HOSE 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	<i>twi</i> 5.00
36	HOLDER, BRAKE HOSE 5 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	<i>twi</i> 5.00
37	HORN P/N: 58186 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	<i>twi</i> 31.00
38	LABOUR P/N: 06766	<i>✱</i> Supply/Install	24.00	\$85.00	<i>1000</i> 2,040.00
39	LAMP SIGNAL FRONT LH P/N: 77864 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	<i>cm</i> 27.00
40	LEG SHIELD P/N: 73879 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	<i>cm</i> 37.00
41	LEG SHIELD 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	<i>cm</i> 37.00

*47048 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
42	LEVER BRAKE LH P/N: 58145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00 ✓
43	LEVER BRAKE RH P/N: 58185 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00 ✓
44	MAIN STAND PAD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	63.00 ✓
45	OBV TYPE B (12V) NEW P/N: 82490 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	341.00 X
46	PANEL 1 LH P/N: 73880 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00 ✓
47	PANEL 2 RH P/N: 77134 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00 ✓
48	PANEL CONSOLE METER P/N: 73885 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00 ✓
49	PANEL INNER 1 P/N: 77868 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00 ✓
50	PANEL, CONSOLE 2 P/N: 83664 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00 ✓
51	PROTECTOR MUFFLER P/N: 76300 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$44.00	44.00 ✓
52	REFLECTOR ASSY REAR P/N: 63813 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00 X
53	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	35.00	\$3.00	105.00 ✓
54	ROTOR SENSOR P/N: 60803 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00 ✓
55	SCREW - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	12.00 ✓
56	SCREW TAPPING P/N: 45991 - (REPORTED BY MECHANIC)	REPLACE	6.00	\$2.00	12.00 ✓

*47048 *

bizSAFE₃

3784

S/N	Description	Action	Qty	Unit Price	Amount
57	SCREW TAPPING (2) P/N: 30678 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$2.00	mer 4.00 ✓
58	SCREW WITH WASHER P/N: 62570 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	mer 10.00 ✓
59	SCREW, TAPPING (3) - (REPORTED BY MECHANIC)	REPLACE	6.00	\$3.00	mer 18.00 ✓
60	SEAL P/N: 83666 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	mer 3.00 ✓
61	SEAL 1 - (REPORTED BY MECHANIC)	REPLACE	3.00	\$5.00	mer 15.00 ✓
62	SEAL OIL FRONT RIM 20X35X7 P/N: 61482 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	mer 12.00 ✓
63	SIDE MIRROR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$94.00	Dange 94.00 ✓
64	SIDE STAND PAD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	Dange 63.00 ✓
65	SPEEDOMETER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$373.00	Dange 373.00 ✓
66	STAY FRONT COWLING P/N: 77865 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$94.00	3rd 94.00 ✓
67	STEERING CONE SET P/N: 71239 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	mer 71.00 ✓
68	STICKER COWLING (WHITE COVER) P/N: 79529 - (REPORTED BY MECHANIC)	✕ REPLACE	1.00	\$8.00	mer 8.00 s/w ✓
69	STICKER COWLING (WHITE COVER) P/N: 79514 - (REPORTED BY MECHANIC)	✕ REPLACE	1.00	\$8.00	mer 8.00 s/w ✓
70	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	✕ REPLACE	1.00	\$30.00	mer 30.00 s/w ✓
71	STOPPER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	mer 8.00 ✓

*47048 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
72	SWITCH, SIDE STAND - (REPORTED BY MECHANIC)	REPLACE	1.00	\$44.00	Damage 44.00 ✓
73	TRANSPORT CHARGES P/N: 07169	*	1.00	\$63.00	35 63.00
74	VALVE TYRE 11.3MM BLACK (RACING VALVE) P/N: 43496 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	Damage 41.00 ✓
75	VISOR AFTERMARKET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	CNA 155.00 ✓
76	WASHER, PLATE P/N: 62251 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$2.00	new 4.00 ✓
77	WHEEL SENSOR ASSY, FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	Damage 50.00 ✓
78	WIRE HARNESS ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$559.00	CNA / Damage 559.00 ✓

SUB TOTAL

\$8,707.00

GST @ 9 %

\$783.63

GRAND TOTAL (SGD)

\$9,490.63

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*47048 *

P-5402
102
P-4861.80
S.W 46
L-1035
5941.80
202
4754

bizSAFE₃