

(08/11/13) waf

ASS. REC. BY:

REF: CS/SMR 24070242/Rvp3


368I

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SNP 23285
 at Workshop m/s PERFORMANCE
 of ALEXANDRA RD
 Insured: SHB 614Z SMR
 Policy No. _____
 Claims No. TAX/07/24/2002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 230K
 IDAC Accident Report: Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNP 23285 Yr Regn: 2024 DM
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: B.M.W 318I LCI ALB c.c. 1998
 Colour WHITE AC: Insured / Std / NI / NA
 Sp. Reading 03593 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: UBA 26FF0108036874
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PR / SUMI /
 TOYO / YOKO or

<u>Front</u>		<u>Rear</u>
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>2/01/24</u>		D.O.I. <u>30/01/24</u>
Survey held at <u>ALEXANDRA</u>		

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 101K

2/9/24 Final fig \$15,548.30 confirmed by email (Red 468.40, 3%)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) S + RS \$ _____

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

→ Strides
12/7/2024

Estimate No. : b1 70384
Date Estimated : 03/07/2024
Prepared By : Tee Hong Da

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Chan Suat Kheng
95 Grange Road
#07-09

Singapore 249616

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNP2328S	WBA20FF0108D36874	19/01/2024	318i Sedan	29

DESCRIPTION

to replace right front and rear door, skirting and rear fender

VALUE

2,550.00

To respray right front and rear door, skirting and rear right fender

2655 3,388.00

To transfer lock mechanism from old to new door including
conduct check on new door power window system for proper
function. (2 doors).

1,062.00

Sundries.

? 80.00

Total Labour 1: **7,090.00****DESCRIPTION**

(S/L) WHEEL ELECTRONICS MODULE RDC ?

QTY**PRIC****VALUE**

ALLOY RIM 7.5JX18 V SPK 780 5m

1

170.50

170.50

WHEEL BOLT BLACK M14X1.25 ?

2

1,141.60

2,283.20

FRT RH SIDE PANEL bt

5

8.75

43.75

FRT RH DOOR bt

1

887.15

887.15

REAR RH DOOR bt

1

1,462.10

1,462.10

(S/L) DOOR WEATHERSTRIP ?

1

1,462.10

1,462.10

RH DOOR SILL COVER PRIMED X

1

165.65

165.65

1

254.15

254.15

Total Parts : **6,728.60**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No financial indication(s) is allowed
- Any damaged item(s) must be resurveyed and
- Must have approval from Insurance Company

Signature: _____

Date: _____

Labour 1 : 7,090.00
Parts : 6,728.60
Labour 2 : 0.00
Excess : 0.00
Total GST @ 9% : 1,243.67
Grand Total : **15,062.27**

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	368I
Vehicle Details	
Vehicle No.:	SNP2328S
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2024
Vehicle Make:	B.M.W.
Vehicle Model:	318I LCI ALED
Primary Colour:	White
Manufacturing Year:	2023
Engine No.:	10987077B48B20A
Chassis No.:	WBA20FF0108D36874
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$48,425.00
Original Registration Date:	19 Jan 2024
First Registration Date:	19 Jan 2024
Transfer Count:	0
Actual ARF Paid:	\$64,008.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2034
PARF Rebate Amount:	\$48,006.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2034
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$85,010.00
COE Rebate Amount:	\$80,462.00
Total Rebate Amount:	\$128,468.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 31 Jul 2024

OK



BMW 3 Series 318i

\$229,888 Instalment \$1,927/mth

PREMIUM AD

Shortlist

Loan Calculator



Overview Financial Photo Research

Depreciation	\$21,020 / year
Reg. Date	28-Dec-2023 (9yrs 4mths 26days COE left)
Manufactured	2023
Mileage	2,222 km
Transmission	Auto
Engine Cap	1,998 cc
Road Tax	\$1,210 / year
Power	115.0 kW (154 bhp) View specs of the BMW 3 Series Sedan (2019)
Curb Weight	1,500 kg
COE	\$110,001
OMV	\$48,425
ARF	\$64,008
Dereg Value	\$136,007 as of today