

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI24070245/Anp3e2(N)	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	03/04/2025	
	ATTN: MADELEIN	E LEE	Code	: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMN 5118T	Veh. Inspected	SGX 73E	
	Policy No.	P10933027R00	Coverage (\$)	0.00	
	Claim No.	C10030511/ML	Excess (\$)	0.00	
	Assign From	CHANG SHI QIAN	Assign Date	15/07/2024	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MITSUOKA GALUE	c.c	2495	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	Y50153254	Colour	GOLD	
	Odometer	184182 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
	L/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
	R/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
	L/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	12/07/2024	Inspection Date	15/07/2024	
	Survey held at	AUTO BAY@ KAKI BUKIT AVENUE 6 ENTRANCE 'A' #01-04			
	Repairer	KT GARAGE PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D)III ACCORDAIN	Estimate Days of Repair			

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: