



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070246/Uqp3
(BUDGET DIRECT INSURANCE)	Date:	14/08/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 6292R	Veh. Inspected	GBL 1786Y
Policy No.	-	Coverage	0
Claim No.	C10030519/MC	Excess	\$0.00
Assign From	CHANG SHI QIAN	Assign Date	15/07/2024

2. Vehicle Details

Make & Model	CITROEN BERLINGO (A)	C.C	1499
Engine No.	10Q4DR0027741	Year of Reg.	30/03/2021
Chassis No.	VR7EFYHZRLJ959153	Colour	WHITE
Odometer	47208 KM	Steering	DAMAGED
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	SUMITOMO	6
L/H Front Tyre	205/60R16	SUMITOMO	6
R/H Rear Tyre	205/60R16	SUMITOMO	6
L/H Rear Tyre	205/60R16	SUMITOMO	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/07/2024	Inspection Date	16/07/2024
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY@KAKI BUKIT, SINGAPORE 417883		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days