

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estn: \_\_\_\_\_  
 OD / TP RES / OD RES / EVA / INV / MV  
 To in Vehicle No: \_\_\_\_\_  
 at W/O \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claimant: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBJ7773E Yr Regn: 2019, August

Type: M.Car / M.Cycle / Bus (Veh) Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV200 C/D 1597

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 107225 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VM20135575

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R14

R: 185/65R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Zeeture

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 16/07/24

Survey held at

Kai Motor

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ALG

COE Expiry

Estimate given during: Yes (✓)

1st Survey: No ( )

MV:

PV:

Nett:

Date/Time, File Pass to?



: Preli. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$

Survey Fee:

Transportation:

3 + R8. \$1

Photos

Others

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |

Report Format:

Report Form A.P. 1 (C)