

ASS. REC. BY:

REF:

C121 CS/CTI24060058/Knce2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YQ 14228

Yr Regn:

09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hino

XBU 700R.C

4009

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading:

181391

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH14UCV3H 70K031882

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

Frisun 700R16x8

Hun R: Lun

(CD)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

55

mm

L/Bal.

6

mm

L/Bal.

55

mm

D.O.A.

10/6/24

D.O.I.

12/6/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

1st O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1. Pls call in the bold note photo
type

29/07/24 submit preli report

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) S + RS. \$

) Fines

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference:
Repairer Reference: 74506
Date calculated: 11/06/2024 5:55 PM

Full Report
Registration: YQ1422Z
Printed: 11/06/2024 5:55 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:		Date of Incident:	10/06/24
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	HINO (Toyota [70])		
Model:	XZU710R 14FT (Dyna - WU6#/WU7#/XZU6#/XZU7# from 07/2011 [1C]/Dyna)		
Sub Model:			
Model Sheet Number:	70 1C 01		
Registration:	YQ1422Z		
VIN number:			
Odometer:	161391		
Model Specs			
FROM 09.2017	AIR CONDITIONING	FOG LAMP ROUND 70W	SIDE FLASHER
AIR FILTER HIGH	4.0 LTR 73KW	TYRES 700 R16	WHEELBASE 3430 MM
STANDARD CAB	TWO COAT METALLIC	PREPARE OFF VEHICLE	

Not within warranty by pain
Ex TAA
7 days

Labour

Code	Description	Time Base 10 WU/h		Price = 42.00 SGD/h	
		WU	Price SGD	WU	Price SGD
NN	R + R R/F WHEELHOUSE COVER	2.0	8.40		
NN	R + R RIGHT FRONT MUD FLAP	1.0	4.20		
NN	RENEW FRONT BUMPER	10.0	42.00		
	INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS				
NN	R + R RADIATOR GRILLE	3.0	12.60		
NN	R + R R/HEADLAMP (RADIATOR GRILLE REMOVED)	1.0	4.20		
	DOES NOT INCLUDE: ADJUST HEADLAMP				
NN	ADJUST HEADLAMPS	3.0	12.60		
NN	R + R WINDSCREEN	30.0	126.00		
	INCLUDES: R + R SUN VISORS, UPPER FRONT PANEL AND A-PILLAR TRIMS				
NN	DETACH + REFIT FRONT FLOOR CARPET	2.0	8.40		
	INCLUDES: R + R FRONT SEATS.				
NN	RENEW R/A-PILLAR	80.0	336.00		
NN	R + R R/F STEP BOARD	3.0	12.60		
NN	RENEW R/F DOOR	14.0	58.80		

Code	Description	WU	Price SGD
	INCLUDES: R + R DOOR, CONVERT ALL ATTACHED PARTS, ADJUST DOOR	1.0	4.20
NN	R + R R/F DOOR HINGE/S	4.0	16.80
NN	DETACH + REFTT HEADLINING	2.0	8.40
NN	R + R R/SEAT	5.0*	21.00
1406	GLASS SPLINTER REMOVE	10.0* 7	42.00
0413	ENGINE FIREWALL REPAIR	15 20.0*	84.00
0936	R/INNER A-PILLAR REPAIR	15 20.0*	84.00
2104	R/R CORNER PILLAR REPAIR	5 20.0*	42.00
1000	REPAIR WIRING REPAIR		
Labour Cost		Hrs	WU
Panel / Mechanical Labour		22.10	221.0
Total of Labour			928.20

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	R/OUTER A-PILLAR NEW PART PAINTING	18.0	
	RIGHT FRONT DOOR NEW PART PAINTING	16.0	
	FRONT BUMPER NEW PART PAINT K1R	7.0	
	R/END MOULDING NEW PART PAINT K1R	3.0	
	ENGINE FIREWALL REPAIR PAINTING <50%	15.0	
	R/R CORNER PILLAR REPAIR PAINTING <50%	9.0	
	R/INNER A-PILLAR SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
0912	R/OUTER A-PILLAR NEW PART PAINTING	19.25
1482	RIGHT FRONT DOOR NEW PART PAINTING	45.92
0281	FRONT BUMPER NEW PART PAINT K1R	26.57
0888	R/END MOULDING NEW PART PAINT K1R	2.95
0413	ENGINE FIREWALL REPAIR PAINTING <50%	24.23
2104	R/R CORNER PILLAR REPAIR PAINTING <50%	8.40
0936	R/INNER A-PILLAR SURFACE PAINT	3.98

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			72.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	10.20	102.0	428.40

Material Cost - Paint

New Part Painting
New Part Painting - Plastic K1R
Repair Painting
Surface-/Blend Paint
Material-constant Metal Preparation
Material-constant Plastic
Total

Price SGD
65.17
29.52
32.63
3.98
28.60
9.00
168.90

Spare Partsprices as at 2015-06-01/01
Price SGD

Code	Description	Part Number	Part Source	Price SGD
1003	300	STICKER	Original	40.00
0281	FRONT BUMPER		Original	420.00
1002	HINO	STICKER	Original	40.00
1394	R/DOOR FRAME TRIM		Original	65.00
1738	R/DOOR MIRROR ASSY		Original	550.00
0888	R/END MOULDING		Original	195.00
1005	R/EURO 6	STICKER	Original	50.00
0294	R/F BUMPER BRACKET		Original	195.00
1006	R/F DOOR SIGNAL	LAMP	Original	50.00
1520	R/F DOOR WINDOW		Original	300.00
0638	R/F FOG LAMP		Original	200.00
2194	R/F INNER SILL MLDG		Original	120.00
1496	R/F LOWER DOOR HINGE		Original	70.00
2206	R/F STEP		Original	180.00
1488	R/F UPPER DOOR HINGE		Original	35.00
1548	R/F WINDOW REGULATOR		Original	100.00
1578	R/INN DOOR LOCK		Original	150.00
0912	R/OUTER A-PILLAR		Original	300.00
1626	R/O WIND GLASS SEAL		Original	45.00
1004	R/WIPER ARM CAP	RENEW	Original	7.00
1007	RH 616	STICKER	Original	50.00
1482	RIGHT FRONT DOOR		Original	950.00
0572	RIGHT HEADLAMP ASSY		Original	420.00
1401	WINDSCREEN		Original	850.00
1410	WINDSCREEN SEAL		Original	85.00
f: OEM Parts				0.00
n: Non-OEM Parts				5,467.00
u: Used parts				5,467.00
Savings				0.00
Subtotal				5,467.00
Total				5,467.00

Extras

Code	Description	Price SGD
1001	IU BRACKET	15.00*
	Total Extras	15.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: Page 3 of 4

PRINT DATE 11/06/2024

Final Calculation

	SGD	SGD
Parts	5,467.00	
Total Parts		5,467.00
Labour Time Base 10 WU/h		
Total 221.0 WU X 42.00 SGD/h	928.20	
Total of Labour		928.20
Total Of Extras		15.00
Paint Work Time Base 10 WU/h		
Labour Cost 102.0 WU X 42.00 SGD/h	428.40	
Material Cost	168.90	
Total Paint Including Material		597.30
Repair Cost Excludes GST		7,007.50
GST (+9.00%)		630.68
Repair Cost Included GST		7,638.18

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	10/06/2024 16:45 (SGT)
Reported by	Actual Driver
Date of Accident	10/06/2024 11:20 (SGT)
Exact Location of Accident	Sungei Kadut Ave, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YQ1422Z
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Avenue Engineering Pte Ltd
Passport No/FIN	GXXXX877N
Email Address	reconiam@jcoeng.com.sg
Mobile Phone No	(Phone) +65-93790498
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Hino
Model	XZU710R 14FT WIDE CAB 5T
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	4009

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMCVSNA00010702404

DRIVER

Name of Driver	Mahalingam Rajesh
Passport No/FIN	GXXXX877N
Date Of Birth	31/05/1985
Occupation	Outdoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use and disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,

(ii) investigating the accident and/or my claims,

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/emails/packages), and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/it may be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

10 JUN 2024


Actual Driver's Signature (if driver is not the policyholder) / Date & Time

10 JUN 2024

Deborah Lai

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you rene

The information contained herein is correct as at 10 Jun 2024

Company

196N

YQ1422Z

No

10 Jun 2024

HINO

XZU710R 14FT WIDE CAB 5T

White

2019

N04CVV10837

JHHUCV3H70K031982

-

\$35,274.00

02 Sep 2019

02 Sep 2019

0

\$1,764.00

No

-

\$0.00

01 Sep 2029

C - Goods Vehicle & Bus

10

\$25,089.00

\$13,111.00

\$13,111.00

OK