

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: CHRYLLIS QUAH

Ref: CS/INC24070271/Aqh3e2(N)

Date: 01/08/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 9331R	Veh. Inspected	SKT 365L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1286270-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	16/07/2024

2. Vehicle Particulars & Condition

Make & Model	PORSCHE 718 BOXSTER	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WP0ZZZ98ZHS231876	Colour	YELLOW
Odometer	58725 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/35 R19	KINFOREST	6 mm
L/H Front Tyre	275/35 R19	KINFOREST	6 mm
R/H Rear Tyre	275/35 R19	KINFOREST	6 mm
L/H Rear Tyre	275/35 R19	KINFOREST	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/07/2024	Inspect Date / Time	16/07/2024 (02:09 PM)
Survey held at	N-51 AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**