

ASS. REC. BY:

REF:

1051

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

825K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SUP 7935E Yr Regn: 01.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Mando 3

C.C.

1496

Colour:

M. Red

A/C: Insured / Std / Nil / NA

Sp. Reading

144413

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JM6BM42A8-G0326560

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/458R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

4

mm

Rear

R/Bal.

5

mm

L/Bal.

4

mm

L/Bal.

5

mm

D.O.A.

15/7/24

D.O.I.

17/7/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P & F damage, w/cp said 1-B.1

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS. SI

: Findings

: Others

Report Format:

Lum Sum / I.B.I: (\$

TOTAL

VINS

Estimated Cost of Repair

Attention To : **ECICS LIMITED**
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/072024/7509
Date : 15-07-2024
Accident Date : 15-07-2024

Vehicle Details

Make & Model : Mazda MAZDA3 4-DOOR SEDAN
1.5L SP.6EAT
Chassis No : JM6BM42A8G0326560
Registration No : SLP7935E

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

S/N	Description	Qty	Amount (\$)
1	RH HEADLAMP	1.00	Bu \$1,300.00 ✓
2	FRONT BUMPER	1.00	Bu/Pr \$480.00 ✓
3	FRONT BUMPER RH NOZZIE GUN	1.00	\$140.00 ?
4	FRONT BUMPER RH NOZZIE GUN COVER	1.00	Pr \$60.00 ✓
5	FRONT BUMPER RH SIGNAL LIGHT	1.00	\$90.00 ?
6	FRONT BUMPER RH FOG LAMP	1.00	Pr \$200.00 X
7	FRONT BUMPER RH FOG LAMP COVER	1.00	Pr \$30.00 ✓
8	FRONT BUMPER RH SIDE RETAINER	1.00	Pr \$10.00 ✓
9	FRONT BUMPER REINFORCEMENT	1.00	Pr \$270.00 X
10	FRONT BUMPER CLIPS	10.00	Pr \$20.00 ✓
11	WIPER TANK	1.00	\$60.00 ?
12	WIPER TANK CAP	1.00	(Pr) \$20.00 X
13	FRONT RH FENDER	1.00	Bu \$180.00 ✓
			\$2,860.00
Margin: 10%			\$286.00
			\$3,146.00
14	TO RESET HEADLAMP SYSTEM	1.00	\$280.00 ?
15	TO REPAIR DAMAGES	1.00	\$580.00 400l
16	TO SPRAY PAINTING	1.00	\$680.00 400l

Subtotal w/o GST:

\$4,686.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Yee Shu Yaw

This is a computer-generated document. No signature is required.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	15/07/2024 16:38 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	15/07/2024 10:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	205D COMPASSVALE LANE MULTI STOREY CAR PARK SINGAPORE 544205
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP7935E
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHAN HUI CHONG, JOSEPH
NRIC No	SXXXX674D
Email Address	JOSEPHCHANHUICHONG@GMAIL.COM
Mobile Phone No	(Phone) +65-96175617
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Policy Number / Cover Note Number	MPC24A00044600

DRIVER

Name of Driver	CHAN HUI CHONG, JOSEPH
NRIC No	SXXXX674D
Date Of Birth	07/10/1988

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


15 JUL 24 / 13:15
Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NR/CID card)

Sketch Plan





**SINGAPORE
POLICE FORCE**



F/20240715/7037

1 of 2

POLICE REPORT (NP299)

Report No. F/20240715/7037

Police Station Of Origin
Ang Mo Kio Division HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-2180000

Date/Time Report Made 15/07/2024 12:19		Vide Report No.		Station Diary No.	
Name Of Informant CHAN HUI CHONG, JOSEPH		Address 206D COMPASSVALE LANE #08-123 SINGAPORE 544206			
ID Type / ID No. NRIC NO / S8838674D		Contact No. Home/Office: Mobile: 96175617			
Nationality SINGAPORE CITIZEN		Email Address JOSEPHCHANHUICHONG@GMAIL.COM			
Occupation Commercial airline pilot		Sex Male	Age 35	Date of Birth 07/10/1988	Race Chinese
Institution/School Name		Language English			
Date/Time Of Incident 15/07/2024 00:15 - 15/07/2024 10:30		Location Of Incident 205D COMPASSVALE LANE MULTI STOREY CAR PARK SINGAPORE 544205			

Brief details.

Came home from work approximately 12:15am and parked at level 4A Lot 309. I remembered parking in between 2 vehicles but unable to remember what type & the number plate of the vehicles.

In the morning around 10:15 as I was heading out, noticed that the right front of my vehicle was found damaged. Car dash camera has no recordings as it does not record when the car is shut down. Suspected a hit & run (park & found) during the period my vehicle was being parked overnight.

Front right of the vehicle was scratched and headlights cracked. (Photos taken) Surveyed around the multi storey carpark area but unable to spot any possible CCTV. However, it would be great if there was CCTV support.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 15/07/2024 12:19
Officer In-Charge Of Case:	Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

Vehicle Details

674D

Vehicle No.:

SLP7935E

Vehicle to be Exported:

No

Intended Deregistration Date:

16 Jul 2024

Vehicle Make:

MAZDA

Vehicle Model:

MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour:

Red

Manufacturing Year:

2015

Engine No.:

P520334832

Chassis No.:

JM6BM42A8G0326560

Maximum Power Output:

88.0 kW (118 bhp)

Open Market Value:

\$18,044.00

Original Registration Date:

27 Jan 2016

First Registration Date:

27 Jan 2016

Transfer Count:

3

Actual ARF Paid:

\$13,044.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

26 Jan 2026

PARF Rebate Amount:

\$7,174.00

Intended COE Rebate Details

COE Expiry Date:

26 Jan 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$45,002.00

COE Rebate Amount:

\$6,871.00

Total Rebate Amount:

\$14,045.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE

The information contained herein is correct as at 15 Jul 2024

OK