

ASSIGNMENT

Front: _____ Date: _____
 Estn: Estimate
 OD / TP RES / OD RES / EVA / INV / MV
 To in Vehicle No: _____
 at Workshop / _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH1019A Yr Regn: 2017, Dec

Type: M.Car / M.Cycle / Bus / Van / Car / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar CD 2953

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 118612 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNISE2F24Z0861118

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C Cordor
 R: 165R13C Windfire

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 25/07/24

One Garage

Date / Time

Action / Instruction

TP INC

COE Expiry

Estimate given during : Yes ()
 1st Survey : No (✓)

MV :

PV :

Nett :

846R

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Report Format :

Report Form / R.P. Form