

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24070276/Avh3m4	
75 BRAS BASAH F		ROAD SINGAPORE 189557	Date:	29/10/2024	
	INCOME CENTRE	SINGAPORE 109007	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 8107M	Veh. Inspected	GBH 1019A	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1286327-002	Excess	\$0.00	
	Assign From	RAJESWARY	Assign Date	17/07/2024	
2. Vehicle Details					
	Make & Model	NISSAN CABSTAR	c.c	2953	
	Engine No.	ZD30027069N	Year of Reg.	29/12/2017	
	Chassis No.	JN1SC2F24Z0861118	Colour	SILVER	
	Odometer	118612 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	195R15C	CONDOR	6	
	L/H Front Tyre	195R15C	CONDOR	6	
	R/H Rear Tyre	165R13C	WINDFORCE	6	
	L/H Rear Tyre	165R13C	WINDFORCE	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	13/07/2024	Inspection Date	25/07/2024 (13:15)	
	Survey held at	ONE GARAGE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					
,					