

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
IS INCOME INSURANCE LTD		Ref:	CS/INC24070277/Anh3
75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Date:	25/09/2024
COME CENTRE S	BINGAPORE 109557	Code:	INC
1. Policy Particulars :- THIRD PARTY CLAIM			
sured Veh.	SMH 6077T	Veh. Inspected	SMN 423K
olicy No.	-	Coverage	0
aim No.	MT/1286504-001	Excess	\$0.00
sign From	JULIE MANGUBAT	Assign Date	17/07/2024
2. Vehicle Details			
ake & Model	HONDA CIVIC	C.C	1595
igine No.	R16A15000220	Year of Reg.	08/09/2011
nassis No.	JHMFD4620AS200165	Colour	BRONZE
dometer	- KM	Steering	IN ORDER
akes	IN ORDER	General	GOOD
odification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
U Eront Turo	225/45R17	KUMHO	6
n Fiolit Tyre			
H Front Tyre	225/45R17	KUMHO	6
	225/45R17 225/45R17	KUMHO KUMHO	6 6
H Front Tyre			
H Front Tyre H Rear Tyre	225/45R17	KUMHO KUMHO	6
H Front Tyre H Rear Tyre H Rear Tyre	225/45R17 225/45R17	KUMHO KUMHO of Damages	6
H Front Tyre H Rear Tyre H Rear Tyre	225/45R17 225/45R17 Description o ED DAMAGES AT THE REAR PORTION	KUMHO KUMHO of Damages	6
H Front Tyre H Rear Tyre H Rear Tyre EHICLE SUSTAINI	225/45R17 225/45R17 Description o ED DAMAGES AT THE REAR PORTION	KUMHO KUMHO of Damages	6
H Front Tyre H Rear Tyre H Rear Tyre EHICLE SUSTAINI	225/45R17 225/45R17 Description of the Description of the DAMAGES AT THE REAR PORTIONS.	KUMHO KUMHO of Damages	6
H Front Tyre H Rear Tyre H Rear Tyre HICLE SUSTAINI GES SEE DETAILS	225/45R17 225/45R17 Description of the Description	KUMHO KUMHO of Damages N. formation Inspection Date	6 6 17/07/2024 (16:17)
H Front Tyre H Rear Tyre H Rear Tyre HICLE SUSTAINI GES SEE DETAILS	225/45R17 225/45R17 Description of ED DAMAGES AT THE REAR PORTION General Info 13/07/2024 KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #	KUMHO KUMHO of Damages N. formation Inspection Date	6 6 17/07/2024 (16:17)
H Front Tyre H Rear Tyre H Rear Tyre HICLE SUSTAINI GES SEE DETAILS cident Date Irvey held at	225/45R17 225/45R17 Description of the properties of the properti	KUMHO KUMHO Formation Inspection Date O1-2020, BEDOK III Tarks JUDICE" BASIS.	6 6 17/07/2024 (16:17) NDUSTRIAL PARK E, SINGAPORE
	BRAS BASAH ROOME CENTRE S ured Veh. icy No. im No. sign From ke & Model gine No. assis No. ometer	Policy Particulars:- Tured Veh. SMH 6077T icy No im No. MT/1286504-001 Sign From JULIE MANGUBAT Vehicle ke & Model HONDA CIVIC gine No. R16A15000220 assis No. JHMFD4620AS200165 ometer - KM lkes IN ORDER diffication(s) RIMS: SPORTS RIM Conditions	Ref: BRAS BASAH ROAD COME CENTRE SINGAPORE 189557 Policy Particulars:- THIRD PARTY CLAI ured Veh. SMH 6077T icy No Coverage im No. MT/1286504-001 Excess sign From JULIE MANGUBAT Assign Date Vehicle Details ke & Model HONDA CIVIC C.C gine No. R16A15000220 Year of Reg. assis No. JHMFD4620AS200165 Colour ometer - KM Steering kes IN ORDER diffication(s) RIMS: SPORTS RIM Conditions of Tyres Size Make

ESTIMATED NORMAL PERIOD FOR REPAIR: 21 Working Days