

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305597757

Via Fax : Small

Date : 16-07-24

Your Insured : SMB 1214

Time of Fax : 16-07-24

Date of Acc. : 16-07-24

Attn: Motor Claims Department

"SMILET BUS"

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH B 6300P

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumanli Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} jumanlibm@cde.com.sg
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

Date/Time: 16.07.2024 16:18

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5947043

JC NO305597757

OMER

S COMFORT TRANSPORTATION PTE LTD

OMER NO 7010045

ESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(R) (O)

(P)

DUNT CARD NO.

REGN NO:

SHB6300P

MILEAGE

MAKE

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4A16.07.2024 13:30

DATE/TIME IN

YR OF MANU

20.12.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU803090463

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 16.07.2024

ATURE: 3P.16.07.24/C

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHB6300P

JU SMRT

Vehicle No.:

SHB6300P

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

DATE: 16.07.24

MVA JUMANI

DOA: 16.07.24

NET
NET

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$503.04
1	REAR BUMPER SIDE BRACKET LH			\$94.80
10	REAR BUMPER CLIPS			\$22.00
1	REAR FENDER LH			\$992.04
1	REAR DOOR ASSY LH			\$1,258.30
1	ROCKER PANEL GARNISH LH			\$576.00
1	WHEEL RIM LH			\$1,555.00
	SUB TOTAL			\$5,001.18
	LESS 25%			\$1,250.04
	DISCOUNTED TOTAL			\$3,750.14
	REAR DOOR APPS LOGO			\$80.00
	PARTOL STICKER			\$40.00
	TOTAL NET			\$120.00
	Labour Charge			
	PANEL BEATING –			\$1,400.00
	SPRAY PAINT			\$1,200.00
	REMOVE/REFIX REVERSE SENSOR			\$50.00
	CHECK WIRING			\$50.00
	TRANSFER DOOR PARTS			\$120.00
	TUFF KOTE			\$50.00
	TOTAL LABOUR			\$2,870.00
	ESTIMATE TOTAL			\$6,740.14
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				