ASS. BY: REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP INS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claim's No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SME4881S Yr Regn: 2018, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic C.C 1597

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 89764 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHFC5650JTC01695

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17

R: 215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	12/06/24

Survey held at MG Solution

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during 1st Survey : Yes (✓) No ( )

Date/Time, File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2)

Report Format :

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Inve ($) ☐ : [illegible] ($

Survey Fee:

Transportation: S + RS. SI

Photos

Others