ComfortDelGro Engineering Pte Ltd (Co. Reg. No. 199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER: CTPL Tokio Marine Insurance Singapore Ltd (HQ)

Thrown

Singapore

PART	ICUL	ARS	OF	CLAIM

Claim Type:

THIRD PARTY

Ref. No:

22/07/2024

Policy No:

Vehicle Reg. No.:

SHA3948X

Date of Loss: Driveable?

VEO.

Party At Fault:

UNKNOWN

YES

Make/Model:

TOYOTA PRIUS HYBRID, 1.8 CVT

Vehicle Reg. Date:

31/05/2019

Vehicle Colour:

TAXI (A) BLUE

Gen Condition:

GOOD

Engine No:

2ZR2C23699

Chassis No:

JTDKB3FU203081046

Odometer:

0 KM

Paint Type:

List Item Discount:

25.00 %

Total Loss?

NO

Est. Duration of Repair

(day)

5

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		3,024.53
Miscellaneous Items		12.00
Labour		2,250.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	5,286.53
	+ GST 9.00% (S\$)	475.79
	Nett Amount (S\$)	5,762.32

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 22 Jul 2024) TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue: Merimen Singapore 1.0)

Parts:

Repairer's

(Price-denominated Standard List)

Labour: Print Code: ComfortDelGro Engineering Pte Ltd/SHA3948X/22/07/2024 12:04

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

	timates on F	Particulars	%Disc	%Depr	Amount
1	1	*REAR BUMPER ASSY / RR	25.00	0.00	*503.04 FL/
2	10	'REAR BUMPER CLIPS / MC	25.00	0.00	*22.00 FL /
3	1	*REAR BUMPER CENTRE MOULDING / JR /(VT	25.00	0.00	*654.96 FL
4	1	*REAR BUMPER UNDER COVER LH X nn	25.00	0.00	*232.00 FL
5	1	*REAR BUMPER AIR DUCT LH /	25.00	0.00	*165.10 FL /
6	1	*REAR FENDER LH / M	25.00	0.00	*992.04 FL
7	1	REAR FENDER SIDE BRACKET LH	25.00	0.00	*94.80 FL /
8	1	*REAR FENDER SHIELD LH X nn	25.00	0.00	*134.20 FL
9	1	*TAILLAMP ASSY UPPER LH / ()	25.00	0.00	*557.90 FL
10	1	*TAILLAMP ASSY LOWER LH / RR	25.00	0.00	*570.00 FL /
11	1	*PATROL STICKER - (4)	0.00	0.00	*30.00 F nett
12	1	*REAR BUMPER MAT / P/C	0.00	0.00	*50.00 F net
F≈F	ranchise part, L=ListIter			0.00	4 006 04

ComfortDelGro Engineering Pte Ltd/SHA3948X/22/07/2024 12:04. Not valid without Reference section. Generated using Merimen e-Claims IEAS

- List Item Discount on L Items (S\$)

3559.84 -25% 2669.88 + 80 nett

Total Parts (S\$)

981.51

3,024.53

Amount

cellaneous Items

OD/TP Case (Insurer)

12.00 /

Sub Total (S\$)

4531.88

L/S - 3625.50 = 3650

12.00

12

Estimates on Labour

LKK Auto Consultants hence notify

 To display damaged part(s) during resurvey · Parts prices are subject to confirmation . Third party survey is on a "Without Prejudice" basis

the Repairer of the following: . To resurvey before/after spray painting

. No illegal modification(s) is allowed · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

No	Particulars	Lab.Type	Amount
<u>Lab</u> 1	OUT Items PANEL BEATING \$\int \forall \cdot \c	New 1140 New Sto	1,500.00 600.00
3	CHECK WIRING TUFF KOTE	New 3	9 50.00 20 50.00
5	REMOVE/REFIX REVERSE SENSOR	1770 New	20 50.00
		Gross Labour Cost (S\$)	2,250.00

ComfortDelGro Engineering Pte Ltd/SHA3948X/22/07/2024 12:04. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ster (LKK)

23/7/24, 3.30pm

L/S

My Ase sy

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRclaim&fuseaction=gen_docview&caseid=1438620&doctype=REPEST&corole=1&...





ComfortDelGro Engineering Pte Ltd

208 Bradded Road Singapore 579 101 Mathère » 25 6063 8060 Facerole » 65 6060 9716

PEGN NO.

Workshops
206 Bracket Road Sequence 179701
50 Livery Drive Sequence 100000
305 Sin May Drive Sequence 570717
Date/Time: *ZedeOffet 19092450001:44

Page: 1

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5947637

JC NO305598318

MILEAGE

共和

COMFORT TRANSPORTATION PTE LTD 7010045 MER 383 SIN MING DRIVE Singapore SINGAPORE 575717

65508755

啊 (P)

KINT CARD NO.

MAKE TOYOTA E____ MODEL PRIUS HYBRID(G4)22.07.2024 09:05 TARGET DATE

YR OF MANUS. 2019

CHASSIS COOF JTD 83FU203081046

COMPLETION DATE/TIME.

cident Date: 22.07.2024


TURE: 3P.22.07.24

NO

LABOR CODE

DESCRIPTION

JOB DESCRIPTION



KED & PASSED OUT BY					an annice and a second
SERVICE ADVISOR		CUSTOMER'S SIGNATURE			
supernerst Stip		Exit Pass			
sha3948X Ju	TOKIO	Vehicle No.:	SHA3948X		
Service Advisor	Signature/Date	Name of Service Advisor	6 -to-workers	Date	
umed to Service Reception upon collection		To be kept by Security G	used		



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withouting of the insurance companies.
 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 Any false reporting may be referred to the Police for Investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission

Reported by

Date of Accident

Exact Location of Accident Additional Location Information

Country/State of Loss

22/07/2024 13:46 (SGT)

Actual Driver

22/07/2024 07:40 (SGT)

Tuas Rd, Singapore

AT THE ROUNDABOUT

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHA3948X

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No

Alternative Phone No

Yes

COMFORT TRANSPORTATION PTE LTD

1XXXXX821R

fleetsafety@cdgtaxi.com.sg

(Phone) +65-98343597

(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

Toyota

Prius

5DR HATCHBACK (AUTO)

Private hire

No - Claiming third party

Taxi

Auto

1798

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

MS First Capital Insurance Ltd

D-24101861MFCT

DRIVER

Name of Driver

NRIC No

Date Of Birth Occupation

KHAIRUL BIN ABU BAKAR

SXXXX733Z

25/03/1979

Outdoor

Accident report SA1K247M000R

Page 1 of 37



Driving Pass Date 13/02/1998 Driving experience 26 YEARS AND 5 MONTHS Gender Male Mobile Number (Phone) +65-98343597 Alt. Phone Number **Email Address** fleetsafety@cdgtaxi.com.sg Address Address complement BLK 344 CHOA CHU KANG LOOP #05-49 Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured No Does Driver Own Other Vehicles? Hirer Vehicle Registration Number of Other Vehicle Owned by Driver No Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Collision - Roundabout Road Surface Clear Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident No Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Number of Passengers (Including Driver) Yes Has the driver been approached by unknown person(s) 3 soliciting/offering accident claims assistance? Translator's name No Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name UNKNOWN Gender Male PASSENGER 2 Name UNKNOWN Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? No No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 22/07/2024 AT ABOUT 0740HRS I WAS DRIVING VEHICLE A(SHA3948X) ALONG TUAS ROAD AT THE ROUNDABOUT AND WANTED TO PROCEED TO PIE CHANGI. WHILE TRAVELLING AT THE MOST EXTREME LEFT LANE THERE WAS A MALAYSIAN VEHICLE WANTED TO CUT INTO MY LANE AND I HAD TO BRAKE AND SOUND THE HONK BUT UNFORTUNATELY VEHICLE B(YP6109B) DID NOT MANAGE TO BRAKE ON TIME AND HIT THE LEFT REAR BUMPER AREA OF MY VEHICLE. NO ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes

Accident report SA1K247M000R

Page 2 of 37



Vehicle Registration Number YP6109B Vehicle Manufacturer Mitsubishi Vehicle Model CANTER FEB21ER4SDEB Vehicle Variant Vehicle Colour Commercial vehicle Vehicle Category Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident



No. Of Passenger (Including Driver)





SKETCH PLAN

IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

1145hrs

Policyholder's Signature / Date &

Sketch Plan

Time

Driver's Signature (if driver is not the policyholder) / Date ^{& Time}22/07/2024

Witnessed by Personnel



AYE TUAS WEST ROAD



Page 4 of 37

William !



Describe Circumstances of the Accident

ON 22/07/2024 AT ABOUT 0740HRS I WAS DRIVING VEHICLE A(SHA3948X) ALONG TUAS ROAD AT THE ROUNDABOUT AND WANTED TO PROCEED TO PIE CHANGI. WHILE TRAVELLING AT THE MOST EXTREME LEFT LANE THERE WAS A MALAYSIAN VEHICLE WANTED TO CUT INTO MY LANE AND I HAD TO BRAKE AND SOUND THE HONK BUT UNFORTUNATELY VEHICLE B(YP6109B) DID NOT MANAGE TO BRAKE ON TIME AND HIT THE LEFT REAR BUMPER AREA OF MY VEHICLE. NO ONE WAS INJURED.

Declaration

VWe declare the foregoing particulars are true in every respect

Driver's Signature (if driver is not the policyholder) / Date & Time

22/07/2024 1145hrs ACM

Witnessed by Reporting Centre Personnel

Accident report SA1K247M000R

Policyholder's Signature / Date &

Page 5 of 37

