

**NCVI INVOLVING  
MDTV (MID 41001) AND  
CIVILIAN BUS (SG5850T)  
ALONG YISHUN AVENUE  
1 ON 23 JULY 2024 AT  
1328H**



Figure A-1: Initial position of the MDTV prior to passing the bus




Figure A-2: Position of MDTV and civilian bus at point of contact



Figure A-3: View of TO at point of contact





Figure B-1: Front View of MID41001



Figure B-2: Rear View of MID41001

Damage assessment: No damage and corresponding yellow paint on MID41001



Figure B-3: G5850 damage - yellow paint marks on the top edge of the left mirror of the bus



STATEMENT

## I (Personal Particulars)

Name: BOOMIRAJ PRAVEEN Alias: \_\_\_\_\_  
 NRIC No: T 142A Rank: CPL Unit: MRF  
 Age: 19 Sex: M Vocation: Combat medic  
 Type of Service: NSF DOE: 02/11/2022 ORD: 01/11/2024  
 Address: \_\_\_\_\_

## II (Statement)

The incident occurred on 23/07/24 around 1325 hr along Yishun Ave and senbawang road. Prior to reaching the traffic junction between Yishun Ave and senbawang road, I kept to the leftmost lane. I noticed the civilian bus ahead of my vehicle on the lane adjacent to my right. I kept to my lane, wished my vehicle closer to the kerb on the left side and carried on driving at a slow 40 km/hr. While the bus was slowly moving off I passed it on its left. I kept on checking my right mirror to make sure there was gap between my vehicle. I did not note any sounds or sensation of contact between the vehicles. As we crossed the traffic light at the junction the bus driver did not honk or show any signal of a vehicle collision for approximately 100m.

## III (Question and Answer) After 100m the bus driver proceeded to

Q1. Speed up, passing by my vehicle before honking and changing lane to abruptly overtake my vehicle signaling me to stop my vehicle. I was asked to exit the vehicle and I turned on the hazard lights. My wheel cracks and asked the driver what happened. He showed me his vehicle left side mirror.

Signature of Serviceman With faint yellow Investigating Officer ==

Date: 23/07/24 scratches and asked me

to inform my superior. Date: \_\_\_\_\_  
 He later demanded my personal particulars and after taking photos he said that I all and left.

Figure C-1: Statement of TO



STATEMENT

## I (Personal Particulars)

Name: Josper Tuen Sang Yung Alias: \_\_\_\_\_  
 NRIC No: 63015 Rank: UD Unit: MRF  
 Age: 21 Sex: M Vocation: CBT Medic  
 Type of Service: NSF DOE: 04/07/23 ORD: 04/07/25  
 Address: \_\_\_\_\_

## II (Statement)

The MRTV was on the left lane before crossing the traffic light while the bus was 1 vehicle length ahead in the adjacent right lane. While passing by the bus (usually in our lane), the MRTV maintained a slow and consistent speed. While passing by the bus I felt no sudden movement and did not hear any sounds. However, the MRTV driver, even checked his right mirror while passing the bus. About 30-45 seconds later the bus driver sped up, caught up to us and told us to pull over at the side of the road. He also cut off our vehicle as we were pulling over. Afterwards we just stopped at the road side and both drivers were talking about what bus happened. However, proceeded to take a photo of the issue. The description of the incident is a yellow scratch on the side view mirrors on the truck was in yellow. After exchanging particulars the bus driver just drove off without saying anything else.

## III (Question and Answer)

Q1.

[Signature]  
 Signature of Serviceman

Date: 23/07/24

[Signature]  
 Investigating Officer

Date:

Figure C-2: Statement of Front Passenger

STATEMENT

## I (Personal Particulars)

Name: Muhammad Haziq Bin Abdul Jalal Alias: \_\_\_\_\_  
 NRIC No: TXXXX918E Rank: LCP Unit: MRF  
 Age: 24 Sex: M Vocation: Combat Medic  
 Type of Service: NSF DOE: 16/05/2023 ORD: 15/05/2025  
 Address: \_\_\_\_\_

## II (Statement)

CPL Praveen was driving along Yishun Ave 1 on 23/07/2024. At the junction going towards Mandai Ave, we passed by a bus that was moving off from the junction. As we passed by the bus, the we were keeping to the left of the lane, nearing to the kerb. There were no sounds could be heard or vibrations felt to show signs of the MDTV grazing with the bus. About 100m past the junction, the bus driver caught up and drove beside us. He horned at us and signalled us to pull over and he cut us off and stopped at the side of the road. Driver ~~the~~ switched on hazard light, dismounted and put the wheel chock on. They then exchanged particulars and called their superiors. The bus driver told CPL Praveen that the side of the MDTV the left side mirror of the bus where there were small scratches on the mirror. However, there were no signs of damage caused by grazing on the MDTV. After exchanging of particulars, the bus driver just drove off.

## III (Question and Answer)

Q1.

Signature of Serviceman

Date: 23/07/2024

Investigating Officer

Date:

Figure C-3: Statement of VC



**SINGAPORE  
POLICE FORCE**



T/20240724/7024

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20240724/7024

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 24/07/2024 10:53		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: BOOMIRAJ PRAVEEN			Address: [REDACTED]		
ID Type / ID No.: NRIC NO / T [REDACTED] 142A			Contact No.: Home/Office:		Mobile: [REDACTED]
Nationality: INDIAN			Email: [REDACTED]		
Sex: Male	Age: 19	Date of Birth: 25/08/2004	Type of Informant: Driver		
Race: Indian			Language: English		
Occupation: National Service Full Time			Driving Licence Information: Class: Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 23/07/2024 13:30	Type of Location: T-Junction
Location:  CHENCHARU LINK				
Weather: Clear		Road Surface: Dry		
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: scratch the bus left side Mirror				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SG5850T	Motor van					0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Figure D-1



**SINGAPORE  
POLICE FORCE**



T/20240724/7024

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20240724/7024

CONTINUATION OF REPORT

Driver			
Name	BOOMIRAJ PRAVEEN	ID No.	T [REDACTED] 142A
Related Vehicle	SG5850T (Motor van)	Contact No.	[REDACTED]
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

**Brief Details.**

The incident occurred on 23/07/24 around 1325 hrs along Yishun Ave 1. Prior to reaching the traffic junction between Yishun Ave 1 and Sembawang Road, I kept to the leftmost lane. I noticed the civilian bus ahead of my vehicle on the lane adjacent to my right.

I kept to my lane, flushed my vehicle closer to the kerb on the left side and carried on driving at a slow 40km/h. While the bus was slowly moving off I passed it on it's left. I kept on checking my right mirror to make sure there was gap between my vehicle and the bus and the heavy vehicle. I did not note any sounds or sensation of contact between the vehicles. As we crossed the traffic light at the junction, the bus driver did not honk or show any signal of a vehicle collision for approximately 100m.

After 100m the bus driver proceeded to speed up, passing by my vehicle before honking and changing lane to overtake my vehicle, signalling me to stop my vehicle.

I was asked to exit the vehicle and I turned on the hazard lights, inserted my wheel chokes and asked the driver what happened. He showed me his vehicle's left side mirror with faint yellow scratches and asked me to inform my superior. He later demanded my personal particulars and after taking photos he said that's all and left.

I got picture of scratches in the Mirror

Figure D-2





**SINGAPORE  
POLICE FORCE**



T/20240724/7024

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20240724/7024

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 24/07/2024 10:53
Officer In Charge Of Case:	Classification Of Case:
NP168	

Figure D-3