

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estn: \_\_\_\_\_  
 OD / TP / TP RES / OD RES / EVA / INV / MV  
 To In \_\_\_\_\_ Vehicle No: \_\_\_\_\_  
 at W \_\_\_\_\_ m/s  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claim No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GB98234D Yr Regn: 2017, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar C.D. 2953

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 247577 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JNISC2F24Z0860378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185R15C BS

R: 155R13C Arino

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. \_\_\_\_\_

\*Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 23/07/24.

Date / Time

Action / Instruction

TP 1st Cap.

COE Expiry

Estimate given during : Yes ( )

1st Survey : No ( )

MV : 36K

PV : 15.4K

Nett : 20.6K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

Survey Fee:

Transportation:

3 + RS. \$

Photos

Others

Report Format:

Report Format: \_\_\_\_\_

**XIN HUA WORKSHOP PTE. LTD.**

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

DATE : 22.07.2024

TO : **1ST CAP INSURANCE**  
VEHICLE NO : **GBG 8234 D**  
MODEL : **NISSAN CABSTAR**  
DATE/TIME ACCIDENT : 07.07.2024 / 2040  
DATE OF REG : 06.11.2017  
CHASSIS : JN1SC2F24Z0860378

**CLAIM DETAIL : PARTS**

| S/N             | DESCRIPTION                             | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----------------|-----------------------------------------|-----|-----------------|------------------|
| 1               | FRONT BUMPER <i>Del'd</i>               | 1   | \$ 785.90       | \$ 785.90 ✓      |
| 2               | HEAD LAMP <i>new</i>                    | 1   | \$ 456.90       | \$ 456.90 +      |
| 3               | HEAD LAMP LOWER GARNISH <i>new</i>      | 1   | \$ 125.60       | \$ 125.60 +      |
| 4               | SIDE MIRROR RH <i>new</i>               | 1   | \$ 205.80       | \$ 205.80 +      |
| 5               | FRONT CORNER PANEL RH <i>Repair</i>     | 1   | \$ 480.20       | \$ 480.20 +      |
| 6               | FRONT DOOR RH <i>Dented</i>             | 1   | \$ 1,696.70     | \$ 1,696.70 ✓    |
| 7               | FRONT DOOR INNER TRIM RH <i>new</i>     | 1   | \$ 785.60       | \$ 785.60 +      |
| 8               | FRONT DOOR HINGE RH <i>new</i>          | 2   | \$ 78.60        | \$ 157.20 +      |
| 9               | FRONT DOOR WEATHER STRIP RH <i>new</i>  | 1   | \$ 192.60       | \$ 192.60 +      |
| 10              | FRONT DOOR INNER LOCK <i>new</i>        | 1   | \$ 186.50       | \$ 186.50 +      |
| 11              | FRONT DOOR LOCK CATCH <i>new</i>        | 1   | \$ 41.20        | \$ 41.20 +       |
| 12              | FRONT DOOR SIGNAL LAMP RH <i>could</i>  | 1   | \$ 53.60        | \$ 53.60 ✓       |
| 13              | FRONT DOOR STEP GARNISH RH <i>could</i> | 1   | \$ 186.30       | \$ 186.30 ✓      |
| 14              | FRONT DOOR STEP PANEL RH <i>Repair</i>  | 1   | \$ 345.20       | \$ 345.20 +      |
| TOTAL PRICE     |                                         |     |                 | \$ 5,699.30      |
| LESS 10%        |                                         |     |                 | \$ 569.93        |
| SUB TOTAL PRICE |                                         |     |                 | \$ 5,129.37      |

TO : 1ST CAP INSURANCE  
 VEHICLE NO : GBG 8234 D  
 MODEL : NISSAN CABSTAR  
 DATE/TIME ACCIDENT : 07.07.2024 / 2040  
 DATE OF REG : 06.11.2017  
 CHASSIS : JN1SC2F24Z0860378

| S/N   | DESCRIPTION                       | QTY | UNIT S/NETT | TOTAL S/NETT |
|-------|-----------------------------------|-----|-------------|--------------|
| 1     | FRONT DOOR COMPANY MARKER STICKER | 1   | \$ 35.00    | \$ 35.00     |
| TOTAL |                                   |     | \$          | 35.00        |

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING**

| S/N   | JOB DESCRIPTION                         | PRICE       | ADJUSTED COST |
|-------|-----------------------------------------|-------------|---------------|
| 1     | TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK | \$ 1,000.00 | 400           |
| 2     | TO PUTTY, SPRAY PAINT, POLISH WAX       | \$ 1,000.00 | 300           |
| 3     | TO SPRAY TUFF COAT                      | \$ 180.00   | 30            |
| 4     | WIRING, BULB CHECKING ON HEADLAMP       | \$ 120.00   | 30            |
| TOTAL |                                         | \$ 2,300.00 |               |

TOTAL PARTS COST : \$ 7,464.37  
 TOTAL LABOUR COST : \$ 2,300.00  
 TOTAL REPAIR COST : \$ 9,764.37

Admaly  
 1/8 23/09/24.  
 03 Days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: