

ASS. REC. BY:

REF:

AIG / 24070374 / KMA3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

-2 days

Res.: Yes or No

Lum Sum: _____

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SNR 49A

Yr Regn: _____

09, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Tesla Model 3

C.C. _____

Colour: _____

m. P. White

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

56270

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

LRW3F7ELXMC 283029

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

255/35ZR20

285/30ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Continental

Front

Rear

R/Bal. _____

7

mm

R/Bal. _____

7

mm

L/Bal. _____

7

mm

L/Bal. _____

7

mm

D.O.A. _____

22/7/24

D.O.I. _____

24/7/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/8

1933.99

Calder

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Transportation: _____

S + RS. SI

: Extras

: Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

Date: 23-7-2024

Vehicle No: SNR49A

Model: Tesla Model 3

Chassis: LRW3F7ELXMC283029

Reg.Year: 3.9.2021

Third Party Insurer: AIG

Third Party Veh No: SJJ121M

Date of Accident: 22/7/2024

Estimator: Loong

Surveyor:

Not Authorised
Pharmacy After Pain
2 day
1933.99

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	mg cm	\$766.00
2	REAR BUMPER LOWER	1	mg cm	\$140.18
3	REAR BUMPER CENTER BRACKET	1		\$52.33
4	REAR BUMPER REINFORCEMENT	1		\$271.02
5	REAR REVERSE SENSOR	1	\$163.55	\$490.65
6	REAR REVERSE SENSOR MOUNTING BRACKET	6	\$4.67	\$28.02
SUB TOTAL				\$1,748.20
LESS 10%				-\$174.82
PARTS TOTAL				\$1,573.38

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		\$55.00
2	REAR BUMPER LOWER CLIPS	1		\$50.00
3	TO RE-COAT OF REAR BUMPER	1		\$130.00
S/N TOTAL				\$235.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$450.00 1801

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, ETC

\$350.00 2201

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 601

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 101

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Branch:

Branch (Motor Insurance Claims)

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3051
Vehicle Details	
Vehicle No.:	SNR49A
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jul 2024
Vehicle Make:	TESLA
Vehicle Model:	MODEL 3 PERFORMANCE
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	-
Chassis No.:	LRW3F7ELXMC283029
Maximum Power Output:	377.0 kW (505 bhp)
Open Market Value:	\$72,143.00
Original Registration Date:	03 Sep 2021
First Registration Date:	03 Sep 2021
Transfer Count:	1
Actual ARF Paid:	\$56,858.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Sep 2031
PARF Rebate Amount:	\$42,643.00
Intended COE Rebate Details	
COE Expiry Date:	02 Sep 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,001.00
COE Rebate Amount:	\$43,374.00
Total Rebate Amount:	\$86,017.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 22 Jul 2024

OK