

ASS. REC. BY:

REF:

C72 / CS/CTI24060069/Kvp3e2

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. SNM24D203389

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

14 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Rear

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/8/24 LS \$40,000 confirmed with Henry (Red 42,439.32, 51%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	842B
Vehicle Details	
Vehicle No.:	SLT1730Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Jun 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 EXCLUSIVE (R18 LED)
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	27492030997526
Chassis No.:	WDD2130422A259516
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$54,744.00
Original Registration Date:	04 Sep 2017
First Registration Date:	04 Sep 2017
Transfer Count:	2
Actual ARF Paid:	\$70,540.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Sep 2027
PARF Rebate Amount:	\$45,851.00
Intended COE Rebate Details	
COE Expiry Date:	03 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,001.00
COE Rebate Amount:	\$16,157.00
Total Rebate Amount:	\$62,008.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 07 Jun 2024

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	11/06/2024 16:30 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	06/06/2024 17:30 (SGT)
Exact Location of Accident	2 Alexandra Rd, Singapore 159919
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT1730Y
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BOSS AUTOMOBILE
Company Reg No	5XXXX842B
Email Address	LIMMRCS@GMAIL.COM
Mobile Phone No	(Phone) +65-97768811
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1991

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMHCSNA00018682300

DRIVER

Name of Driver	CHO KAI LONG VINCENT
NRIC No	SXXXX880B
Date Of Birth	10/08/1992
Occupation	Outdoor

Driving Pass Date	05/03/2020
Driving experience	4 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98188131
Alt. Phone Number	-
Email Address	CHO.KL.VINCENT@GMAIL.COM
Address	6 HOLLAND CLOSE #20-30
Address complement	-
Postcode	271006
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Clementi Division Headquarters
Police Station Phone No	(Phone) +65-18007740000
Alt. Police Station Phone No	(Fax) +65-67741705
Police Station Address	20 Clementi Avenue 5 Singapore 129858
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG4980D
Vehicle Manufacturer	Honda
Vehicle Model	Civic
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	WOO JIAN SHENG
Contact Number	(Phone) +65-96967860
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLL5488M
Vehicle Manufacturer	Mazda
Vehicle Model	Biante
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	DANNY
Contact Number	(Phone) +65-88122798
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	CHO KAI LONG VINCENT
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	CHEST , NECK, SHOULDER & LEG PAIN
Injured person in which vehicle?	SLT1730Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

Describe Circumstances of the Accident

REFER TO POLICE REPORT

D / 10040610 / 7006

Declaration

~~I~~We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



**SINGAPORE
POLICE FORCE**



D/20240610/7006

1 of 1

Report No. D/20240610/7006

POLICE REPORT (NP299)

Police Station Of Origin
Clementi Division HQ
6 Lempeng Drive SINGAPORE 128496
Tel No: 1800-7740000

Date/Time Report Made 10/06/2024 09:41	Vide Report No.		Station Diary No.	
Name Of Informant CHO KAI LONG VINCENT	Address 6 HOLLAND CLOSE #20-30 SINGAPORE 271006			
ID Type / ID No. NRIC NO / S9226880B	Contact No. Home/Office:		Mobile: 98188131	
Nationality SINGAPORE CITIZEN	Email Address CHO.KL.VINCENT@GMAIL.COM			
Occupation Real estate agent	Sex Male	Age 31	Date of Birth 10/08/1992	Race Chinese
Institution/School Name	Language English			
Date/Time Of Incident 06/06/2024 17:30 - 06/06/2024 18:00	Location Of Incident 6 HOLLAND CLOSE #20-30 SINGAPORE 271006			

Brief details.

On 06/06/24 at about 5.30pm, I was caught into an accident. Report number : E/20240606/0125

I was driving SLT1730Y along Alexandra road, my phone dropped from my phone holder, I was distracted for a second. When I looked up, I jam brake but couldn't stop in time and collide into the car in front of me.

After the accident, I went to Mount Elizabeth hospital for a check up, chest pain with contusion and tenderness, abrasions over left knee and right leg. I was admitted into the hospital till 08/06/24 and was granted hospitalisation leave from 06/06/24 to 17/06/24. MC Number : PNH-2024-012177.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 10/06/2024 09:41
Officer In-Charge Of Case:	Classification Of Case:

Ding Auto Pte Ltd
Sin Ming Industrial Est. Sec C, Blk
10,#01-20
575645



Insurer Reference:
Repairer Reference: 070863
Date calculated: 11/06/2024 6:09 PM

Full Report
Registration: SLT1730Y
Printed: 11/06/2024 6:09 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:		Date of Incident:	06/06/24
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	E-CLASS (W213)
Sub Model:	E 200
Model Sheet Number:	03 FE 42
Registration:	SLT1730Y
VIN number:	
Odometer:	189160

Not Authorized
11 Day @
Recovery After Repair
Ex \$2000p
14 days

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	----------------------------	---------------------------	---------------------------	----------------------------	----------------------------	-----------------------------	-----------

Spare Tyre Brand	Tread (Spare), mm
------------------	-------------------

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	12.60
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		3.0	12.60
54-0650 01	MAIN BOARD MAINTAINED (FOR CHECK AND DIAGNOSIS WORK)		1.0	4.20
61-1069 01	R + R COMPL LWR ENGINE COMPARTMENT COVER		3.0	12.60
88-2532 01	REPAIR OF FRONT-END DAMAGE INCLUDES: RENEW BUMPER, BONNET, RADIATOR COVER, FRONT WINGS AND FRONT LAMP UNITS, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		44.0	184.80
88-2657 01	R + R BOTH BONNET HINGE		4.0	16.80
88-2620 01	R + R FRONT BONNET CABLE		3.0	12.60

Code	Description	WU	Price SGD
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT MODULE INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION	15.0	63.00
62-1266 01	R + R OR RENEW FRONT CROSSMEMBER AND COMPLETE TRUSSING BETWEEN WHEELHOUSES INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY	15.0	63.00
62-1440 01	RENEW L/F SIDE MEMBER END SECTION	21.0	88.20
62-1441 01	RENEW R/F SIDE MEMBER END SECTION	21.0	88.20
67-1700 01	RENEW FRONT SCREEN INCLUDES: INTERIOR MIRROR, RAIN SENSOR, BOTH WIPER ARMS, COVER WATER BOX, COVER MOULDINGS AND ALL TRIMS REMOVE AND REFIT	26.0	109.20
68-4605 01	R + R INSTRUMENT PANEL	27.0	113.40
68-4635 01	RENEW INSTRUMENT PANEL (REMOVED)	4.0	16.80
68-7681 01	R + R INDICATOR SWITCH	7.0	29.40
68-5070 02	RENEW ALTERNATOR	15.0	63.00
20-3865 01)	R + R RADIATOR	7.0	29.40
20-5410 02	R + R OVERFLOW TANK	8.0	33.60
09-6935 03)	R + R LOW-TEMPERATURE COOLER (ADD)	3.0	12.60
83-6543 01	R + R AIR CONDITIONING CONDENSER	14.0	58.80
83-7351 04)	R + R AIR CONDITIONING COMPRESSOR	4.0	16.80
83-7383 01	RENEW COMPRESSOR AIR CONDITION REMOVED	3.0	12.60
83-7805 ZAX	REMOVE AND REFIT WATER PIPE A	4.0	16.80
83-7810 ZAX	REMOVE AND REFIT WATER PIPE B	4.0	16.80
83-7820 ZAX	REMOVE AND REFIT WATER PIPE D	4.0	16.80
33-1050 01	R + R FRONT AXLE CARRIER	40.0	168.00
33-1252 ZAX	RENEW FRONT AXLE SUPPORT (REMOVED)	1.0	4.20
33-1427 02	R + R LEFT FRONT CONTROL ARM	7.0	29.40
33-1428 02	R + R RIGHT FRONT CONTROL ARM	7.0	29.40
33-1411 01)	REMOVE AND REFIT L/F CONTROL ARM	5.0	21.00
33-1411 01)	REMOVE AND REFIT R/F CONTROL ARM	5.0	21.00
20-1190 01	ADDITION TO COOLING SYSTEM DRAIN /REFILL (VEHICLE WITH SEPARATE LOW TEMPERATURE-WATER CYCLE)	3.0	12.60
68-1762 01	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	6.0	25.20
83-0640 01	CHECK AIR COND	1.0	4.20
82-1110 01	ADJUST HEADLAMPS	3.0	12.60
40-6500 01	ALIGN VEHICLE INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER, CHECK FRONT AND REAR VEHICLE LEVEL	8.0	33.60

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	34.10	341.0	1,432.20
Alignment			
Measuring Work	0.80	8.0	33.60
Total of Labour			1,465.80

Paint

Paint Work

Time Basis 10 WU/h

Code	Description - MF	WU	Price SGD
98-1731 01	FRONT BUMPER TRIM PAINTING	8.0	33.60
98-2805 01	BONNET PAINTING STAGE I-M	26.0	109.20
98-2005 ZAX	L/BONNET HINGE PAINTING STAGE I-J	3.0	12.60
98-2005 ZAX	R/BONNET HINGE PAINTING STAGE I-J	3.0	12.60
98-2415 01	L/F WING PAINTING STAGE I-M	7.0	29.40
98-2615 01	R/F WING PAINTING STAGE I-M	7.0	29.40
LE 1211	L/F SIDE MEMBER END PAINTING STAGE I-J	6.0	25.20
LE 1212	R/F SIDE MEMBER END PAINTING STAGE I-J	6.0	25.20
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	14.0	58.80

Total Paint

Hrs 8.00 WU 80.0 Price SGD 336.00

Material Cost - Paint

Inner Part Painting
New Part Painting (Bold)
Material-constant Metal
Total

Price SGD
7.48
171.57
13.47
192.52

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0257	FRONT NUMBER PLATE	KNPL3	Original	Mi's	30.00 ✓
0260	FRT NO PLATE BRKT	213 880 0044	Original	Mi's	110.00 ✓
0283	FRONT BUMPER TRIM	213 885 0038649999	Original	Bu	1,650.00 ✓
0291	FRT UPP BUMPER SEAL	205 628 1300	Original	Mi's	75.00 ✓
0299	TOWING EYE COVER	213 885 0222 9999	Original	Mi's	140.00 ✓
0303	L/F BUMP LWR GRILLE	213 885 0922	Original	CR	145.00 ✓
0304	R/F BUMP LWR GRILLE	213 885 1022	Original	CR	145.00 ✓
0305	FRT CT BUMP GRILLE	213 885 0622	Original	Bu	180.00 ✓
0317	FRT LWR BUMPER MLDG	213 885 0100	Original	Bu	175.00 ✓
0335	FRT CTR BUMPER CARR	213 885 1265	Original	Bu	185.00 ✓
0343	L/F BUMPER CARRIER	213 885 0865	Original	Bu	185.00 ✓
0344	R/F BUMPER CARRIER	213 885 1065	Original	Bu	185.00 ✓
0349	FRT/CTR IMPACT DAMP	213 885 0237	Original	Bu	280.00 ✓
0381	OUTER TEMP SENSOR	007 542 1318	Original	Mi's	180.00 ✓
0390	CTR FRT BUMPER MLDG	213 885 7401	Original	Bu	160.00 ✓
0405	GRILLE	213 880 8602	Original	Bu	1,050.00 ✓
0415	L/F AIR GUIDE GRILLE	213 505 1130	Original	Mi's	120.00 ✓
0416	R/F AIR GUIDE GRILLE	213 505 1230	Original	Mi's	120.00 ✓
0432	FRONT MANUFACT BADGE	221 880 0086	Original	Mi's	120.00 ✓
0471	BONNET	213 880 0357	Original	Bu	2,450.00 ✓
0475	L/BONNET HINGE	213 880 0128	Original		320.00 ?
0476	R/BONNET HINGE	213 880 0228	Original		320.00 ?

Code	Description	Part Number	Part Source	Price SGD	
0481	CTR BONNET INSULAT	213 682 0026	Original	De form 480.00	✓
0485	L/F SUSPN BUFFER	000 998 7340	Original	20.00	?
0486	R/F SUSPN BUFFER	000 998 7340	Original	20.00	?
0494	BONNET CATCH	218 880 0064	Original	Ry 120.00	✓
0495	L/ACCELERATION SENS	213 905 1300	Original	180.00	?
0496	R/ACCELERATION SENS	213 905 1300	Original	180.00	?
0497	L/F BONNET STRUT	213 980 0164	Original	Sm 145.00	X
0498	R/F BONNET STRUT	213 980 0264	Original	Sm 145.00	X
0500	BONNET CABLE	257 880 2304	Original	95.00	?
0503	L/UPP LOCK	213 880 0060	Original	Ry 115.00	✓
0504	R/UPPER LOCK	213 880 0060	Original	Ry 115.00	✓
0507	L/SPRING ELEMENT	205 880 0027	Original	55.00	?
0508	R/SPRING ELEMENT	205 880 0027	Original	55.00	?
0515	L/LID LOCKING	204 880 0260	Original	DIT 55.00	—
0516	R/LID LOCKING	204 880 0260	Original	DIT 55.00	—
0521	L/LWR HEADLAMP BRKT	213 620 2800	Original	Ry 45.00	—
0522	R/LWR HEADLAMP BRKT	213 620 2900	Original	Ry 45.00	—
0561	LEFT HEADLAMP ASSY	213 820 2361	Original	Ry 3,600.00	—
0562	RIGHT HEADLAMP ASSY	213 820 2461	Original	Ry 3,600.00	—
0541	L/F WING	213 880 0118	Original	Ry 1,150.00	✓
0542	R/F WING	213 880 0018	Original	Ry 1,150.00	X
0839	L/F W-HOUSE FRT CVR	238 690 1303	Original	CM 170.00	—
0840	R/F W-HOUSE FRT CVR	238 690 1403	Original	CM 170.00	—
0841	L/F W-HOUSE RR COVER	238 691 1700	Original	Sm 295.00	X
0842	R/F W-HOUSE RR COVER	238 691 1000	Original	295.00	?
0930	FRONT MODULE CPL	213 620 6300	Original	1,150.00	?
0935	UPP FRT PANEL COVER	213 620 1701	Original	CM 290.00	—
0955	L/F C-MEMBER STRUT	213 620 2700	Original	Ry 85.00	—
0956	R/F C-MEMBER STRUT	213 620 2700	Original	Ry 85.00	—
0989	FRONT CTR RETAINER	213 898 0100	Original	CM 110.00	—
1001	FRT LWR CROSSMEMBER	213 620 0130	Original	580.00	?
1187	L/F LWR BUMP FRT ABS	213 620 0400	Original	140.00	?
1188	R/F LWR BUMP FRT ABS	213 620 0400	Original	140.00	?
1189	L/F STRUT	253 620 1600	Original	85.00	?
1190	R/F STRUT	253 620 0700	Original	85.00	?
1191	L/F UPP BUMP FRT ABS	213 620 0195	Original	Ry 210.00	—
1192	R/F UPP BUMP FRT ABS	213 620 0295	Original	Ry 240.00	—
1211	L/F SIDE MEMBER END	213 620 8900	Original	1,750.00	?
1212	R/F SIDE MEMBER END	213 620 9000	Original	1,750.00	?
1401	WINDSCREEN	213 670 8002	Original	CM 1,050.00	✓
1411	WINDSCREEN REP KIT	000 989 4905 11		0.00	
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS			
1416	WINDSCREEN SEAL	000 987 4866	Original	Sm 120.00	—
1441	WASHER JET COVERS	205 869 0007	Original	mit 450.00	—
4325	PASSENGER AIRBAG	213 860 0202	Original	Ry 1,980.00	—
4331	INSTRUMENT PANEL	213 680 9504	Original	Ty 5,500.00	—
		9K00			
4455	AIR CON COMPRESSOR	000 830 3002	Original	3,350.00	?
4465	AIR CON CONDENSER	099 500 0454	Original	Ry 1,780.00	✓
4469	L/RADIATOR SUPP FRAM	099 504 1800	Original	Ry 120.00	—
4470	R/RADIATOR SUPP FRAM	099 504 2000	Original	Ry 120.00	—
4481	PUMP/DRYER PIPE	213 830 1502	Original	135.00	?
4482	CONT/EXP VALVE PIPE	213 830 5100	Original	220.00	?
4483	COMPRESSOR PIPE	205 830 6201	Original	150.00	?
7011	FRONT AXLE SUPPORT	205 628 0057	Original	2,850.00	?
7047	L/F TENSION ROD	205 330 1305	Original	Sm 390.00	X

Code	Description	Part Number	Part Source	Price SGD	
7048	R/F TENSION ROD	205 330 1405	Original	Per 390.00	X
7071	L/F CONTROL ARM	205 330 6510	Original	Per 680.00	X
7072	R/F CONTROL ARM	205 330 6610	Original	Per 680.00	X
7261	FRONT STABILIZER	205 323 2700	Original	Per 380.00	X
7415	COMBI SWITCH MODULE	213 900 7010 9051	Original	350.00	?
7445	DRIVER AIRBAG	000 860 1002 9116	Original	Burn 2,900.00	✓
7751	FRONT INTAKE CHANNEL	213 500 0055	Original	CM 195.00	✓
7752	LOWER AIR GUIDE	213 505 0130	Original	CM 205.00	✓
7753	RADIATOR AIR GUIDE	213 505 0030	Original	CM 195.00	✓
7761	RADIATOR	099 500 2203	Original	1,450.00	?
7762	LOW TEMP RADIATOR	099 500 2003	Original	1,350.00	?
7765	L/LWR RADIATOR BRKT	213 501 0620	Original	150.00	?
7766	R/LWR RADIATOR BRKT	213 501 0720	Original	150.00	?
7773	R/RADIATOR HOSE	253 501 9382	Original	85.00	?
7776	L/RADIATOR HOSE	253 501 9182	Original	85.00	?
7787	EXPANSION TANK	205 500 0049	Original	Per 215.00	X
7789	FAN UNIT	099 906 1800	Original	1,950.00	?
8249	WASHER BOTTLE	274 200 0385	Original	Per 185.00	X
8383	AIR SUCTION TUBE	274 090 0029	Original	225.00	?
8385	AIR INTAKE HOSE	274 090 1800	Original	165.00	?
8391	AIR FILTER	274 090 1701 64	Original	Per 550.00	X
8411	ALTERNATOR	000 906 0922	Original	Per 3,350.00	X
8775	L/F LOWER COVER	213 520 5600	Original	CM 105.00	✓
8776	R/F LOWER COVER	213 520 5800	Original	CM 105.00	✓
8779	FRT ENGINE COVER	213 520 0000	Original	350.00	?
8780	CTR LWR ENGINE CVR	213 524 2700	Original	850.00	?
9645	L/HORN	213 542 4400	Original	200.00	?
9646	R/HORN	213 542 4300	Original	200.00	?
9684	L/F CONTACT SWITCH	204 870 3158	Original	80.00	?
9685	R/F CONTACT SWITCH	204 870 4458	Original	80.00	?
1000	BONNET ACTUATOR RH	ACTUATOR	Original	Per 250.00	X
1001	BONNET ACTUATOR LH	ACTUATOR	Original	Per 250.00	X
1002	FRT PARKING SENSOR	SENSOR(X4)	Original	Per 760.00	✓
1003	PARKING SENSOR SIDE	SENSOR(X2)	Original	380.00	?
1004	F/SENSOR HARNESS	SENSOR HARNESS	Original	590.00	?
1005	FRT RADAR SENSOR	RADAR	Original	1,650.00	?
1006	RADAR SENSOR	RADAR	Original	55.00	?
1007	BRACKET				
1007	FRT GRILLE CAMERA	CAMERA	Original	1,800.00	?
1008	KNEE AIRBAG RH	AIRBAG	Original	Burn 1,350.00	✓
1009	KNEE AIRBAG COVER RH	COVER	Original	Per 250.00	✓
1010	AIRBAG ECU CPL	ECU	Original	Per 1,150.00	✓
1011	SEAT BELT FRT RH	SEAT BELT	Original	Per 1,590.00	✓
1012	SEAT BELT FRT LH	SEAT BELT	Original	Per 1,590.00	✓
1013	SEAT BELT BUCKLE RH	BUCKLE FRONT	Original	180.00	?
1014	SEAT BELT BUCKLE LH	BUCKLE FRONT	Original	180.00	?
1015	SEAT BELT REAR RH	SEAT BELT	Original	Per 590.00	✓
1016	SEAT BELT REAR LH	SEAT BELT	Original	Per 590.00	✓
1017	SEAT BELT BUCKLE RH	BUCKLE REAR	Original	220.00	?
1018	SEAT BELT BUCKLE LH	BUCKLE REAR	Original	220.00	?

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

0.00
77,095.00
77,095.00

Acknowledged by Repairer

Signature:

Date:

Final Calculation

	SGD	SGD
Parts	77,095.00	
Total Parts		77,095.00
Labour Time Base 10 WU/h		
Total 341.0 WU X 42.00 SGD/h	1,432.20	
Alignment		
Measuring Work	33.60	
Total of Labour		1,465.80
Paint Work Time Base 10 WU/h		
Labour Cost 80.0 WU X 42.00 SGD/h	336.00	
Material Cost	192.52	
Total Paint Including Material		528.52
Repair Cost Excludes GST		79,089.32
GST (+9.00%)		7,118.04
Repair Cost Included GST		86,207.36

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.