

Accident Repair Estimate

ACCIDENT DATE: 17-Jul-24

BUS NUMBER: SBS86592

ACCIDENT TIME: 0536Hrs

BUS MODEL: WSD

ACCIDENT REPORT NUMBER: AR-2024-3861

DATE OF SURVEY: 25-Jul-24

3RD PARTY CLAIM AGAINST: PCS067U

SECTION A:

PARTS & MATERIAL COST

Part or Item Description	Quantity	Total Cost
REAR WINDSCREEN..SN C&D	1	\$170.00
REAR DOOR;F/GLASS;C & C+ SERIES	1	\$523.00
BUMPER,REAR,F/G.C&D SERIES	1	\$305.00
RR LAMP PANEL;O/S	1	\$162.00
LED TAIL/STOP LAMP	2	\$194.40
LED INDICATOR LAMP	1	\$102.20
LED REVERSE LAMP	1	\$105.60
REFLEX REFLECTOR	1	\$1.35
STKR SBS TRANSIT RR SD/DD	1	\$6.00
SIDE PANEL JR*KR.O/S.SIDE PANEL ASSY	1	\$250.00
REAR FRAME PILLAR;RR FRAME	1	\$153.00
ATTACHMENT BRACKET BOTTOM;RR FRAME	1	\$57.14
SKID SHOE @ K;RR FRAME	1	\$56.70
VERTICAL PILLAR @ KL+KR;SIDE FRAME	1	\$228.60
GAS JACK 0400N;RR ENG DOOR	2	\$52.00
LIMIT SWITCH;ADJUSTABLE @ RR ENG DR	1	\$23.13
FLUID RESERVOIR;HYD.PMP	1	\$180.49
COMPARTMENT HINGE LHS 1@ HL	1	\$122.10
COMPARTMENT HINGE RHS 1@ JL	1	\$122.10
DOOR FRAME JR*KR;O/S;ALUM;A/B/C SERIES	1	\$163.80
INSULATION 01;CPSS25;25MMX1MX2M;WIRING	1	\$149.13
INSULATION HOLDER 01;1.0MM ALUM SHEET N	1	\$33.42
ALUM WIRE MESH;ENG DR;1PC=1.8M N	1	\$172.60
	1	
TOTAL PARTS & MATERIAL COST		\$3,333.76

SECTION B:

ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)

Assessment of Bus (With Damaged)	\$188.00
To Remove / Replace / Repair Damaged Parts by Contractor	\$3,800.00
To Remove/ Replace/ Repair Damaged Advertisement Panel	\$0.00
TOTAL LABOUR COST	\$3,988.00

SECTION C:

SUMMARY

Total Repair Costs	\$7,321.76
Total Downtime (Days)	5
Towing Cost	\$0.00
Total Overheads Costs	\$2,196.53
TOTAL COST	\$11,558.79

*Please kindly note that the downtime (days) is just an estimate.

*Please undersign to acknowledge this repair estimate.

Prepared by:

ERIC NG
Snr Technical Officer
Ulu Pandan Workshop
Bus Engineering

Surveyor Name & Contact:

Rasul - Hp 90010068

Signature:

Signature:

Far

Date:

Date:

25/7/24

25/07/24

Resy 14 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: