

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliate data Fadamatian Intermedianala Dea Francata Fa Automobile					
Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN		Ref:	CS/INC24060007/Aqp3	
	75 BRAS BASAH R	OAD SINGAPORE 189557	Date:	25/09/2024	
	THOUSE CENTRE	Sirver ii Oric 188887	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBT 471U	Veh. Inspected	SNC 2354J	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1278688-003	Excess	\$0.00	
	Assign From	HAZALYSA	Assign Date	10/06/2024	
2. Vehicle Details					
	Make & Model	HONDA VEZEL	C.C	1496	
	Engine No.	L15Z1000555	Year of Reg.	04/10/2021	
	Chassis No.	RV31000395	Colour	GOLD	
	Odometer	59721 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60 R16	DUNLOP	6	
	L/H Front Tyre	215/60 R16	DUNLOP	6	
	R/H Rear Tyre	215/60 R16	DUNLOP	6	
	L/H Rear Tyre	215/60 R16	DUNLOP	6	
	4. Description of Damages				
4.					
	VEHICLE SUSTAIN	ED DAMAGES AT THE FRONT O/S PC			
THE	VEHICLE SUSTAIN				
THE			PRTION.		
THE		S.	PRTION.	10/06/2024 (11:48)	
THE	MAGES SEE DETAIL	S. General In t	formation Inspection Date JKIT AVE 4 (SOUTH	,	
THE	Accident Date	S. General Into 21/05/2024 MG SOLUTION PTE LTD - 23 KAKI BU	formation Inspection Date JKIT AVE 4 (SOUTH	,	
THE DAM 5. 5a. A) TI	Accident Date Survey held at HE INSPECTION WA	General Int 21/05/2024 MG SOLUTION PTE LTD - 23 KAKI BU INSPECTION CENTRE, SINGAPORE	formation Inspection Date JKIT AVE 4 (SOUTH 415933 Arks JUDICE" BASIS.	H WING) #02-03B VICOM	

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days