



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

|                                |       |                       |
|--------------------------------|-------|-----------------------|
| MS INCOME INSURANCE LTD        | Ref:  | CS/INC24070395/Anh3m4 |
| 75 BRAS BASAH ROAD             | Date: | 28/10/2024            |
| INCOME CENTRE SINGAPORE 189557 | Code: | INC                   |

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | GBM 8798L      | Veh. Inspected | GBL 2983M  |
| Policy No.   | -              | Coverage       | 0          |
| Claim No.    | MT/1287506-002 | Excess         | \$0.00     |
| Assign From  | YEE PEI LI     | Assign Date    | 25/07/2024 |

### 2. Vehicle Details

|                 |              |              |            |
|-----------------|--------------|--------------|------------|
| Make & Model    | NISSAN NV200 | C.C          | 1597       |
| Engine No.      | HR16181136D  | Year of Reg. | 28/04/2021 |
| Chassis No.     | VM20163747   | Colour       | GREY       |
| Odometer        | 82232 KM     | Steering     | IN ORDER   |
| Brakes          | IN ORDER     | General      | GOOD       |
| Modification(s) | RIMS: NIL    |              |            |

### 3. Conditions of Tyres

|                | Size    | Make   | Balance (mm) |
|----------------|---------|--------|--------------|
| R/H Front Tyre | 165R14C | FALKEN | 6            |
| L/H Front Tyre | 165R14C | FALKEN | 6            |
| R/H Rear Tyre  | 165R14C | FALKEN | 6            |
| L/H Rear Tyre  | 165R14C | FALKEN | 6            |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

|                |  |                 |                    |
|----------------|--|-----------------|--------------------|
| Accident Date  | 23/07/2024   | Inspection Date | 25/07/2024 (14:02) |
| Survey held at | HD PERFECT AUTOWORK PTE LTD<br>8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875 |                 |                    |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days