



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070399/Kqp3e2
(BUDGET DIRECT INSURANCE)	Date:	23/09/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 7675R	Veh. Inspected	SLN 8187B
Policy No.	P10744512R02	Coverage	0
Claim No.	C10030708 /JK	Excess	\$0.00
Assign From	LAN BOON CHIN	Assign Date	25/07/2024

2. Vehicle Details

Make & Model	HONDA VEZEL (A)	C.C	1496
Engine No.	L15B4403826	Year of Reg.	18/05/2017
Chassis No.	RU11203826	Colour	METALLIC GREY
Odometer	108160 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/65R16	DUNLOP	7
L/H Front Tyre	215/65R16	DUNLOP	7
R/H Rear Tyre	215/65R16	DUNLOP	6
L/H Rear Tyre	215/65R16	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/07/2024	Inspection Date	25/07/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days