



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24060072/Aqh3e2
50 RAFFLES PLACE #03-03	Date:	18/10/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBM 1009C	Veh. Inspected	SNB 8266X
Policy No.	-	Coverage	0
Claim No.	CMTD2401912/JYC	Excess	\$0.00
Assign From	GRACE TEO	Assign Date	12/06/2024

2. Vehicle Details

Make & Model	HONDA VEZEL	C.C	1496
Engine No.	L15Z1000951	Year of Reg.	29/09/2021
Chassis No.	RV31000760	Colour	WHITE
Odometer	77410 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60 R16	HANKOOK	6
L/H Front Tyre	215/60 R16	HANKOOK	6
R/H Rear Tyre	215/60 R16	HANKOOK	6
L/H Rear Tyre	215/60 R16	HANKOOK	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/06/2024	Inspection Date	12/06/2024
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days