



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWERSINGAPORE 048583 ATTN: QUY			Ref: CS/LIP24070420/Avh3m4(N) Date: 11/09/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLH 5129X	Veh. Inspected	PD 3378E
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS24/2305	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	25/07/2024
2. Vehicle Particulars & Condition				
	Make & Model	VOLVO B11R	c.c	10837
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	YV3T2U82XNA209799	Colour	GOLD
	Odometer	65547 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	PIRELLI	8 mm
	L/H Front Tyre	295/80 R22.5	PIRELLI	8 mm
	R/H Rear Tyre	295/80 R22.5	PIRELLI	8 mm
	L/H Rear Tyre	295/80 R22.5	PIRELLI	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/07/2024	Inspection Date	06/08/2024
	Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		
5a. Remarks				
	A)REGISTRATION DATE: 18 OCT 2023 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	