

LIBERTY

ASSIGNMENT

Veh No: **FBU1496L** Yr Regn: **26 Aug 2022**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **YAMAHA NMAX** C.C **155**

Colour **Black** A/C: Insured / Std / NI / NA

Sp. Reading 3256 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3SG5680NK139527

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70-13

R: 130/70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or PIRELLI

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 19/07/24 D.O.I. 29/07/24

Survey held at **City Bike Rental**

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]☐: Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$

☐ Interview (\$

$$S + RS \rightarrow SI$$

Photos

Tech. Invs (\$)

Others

☐ Weekend (\$\$)

TOTAL

LEADIN SMOKE / L.B.I. 65