

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
Me	LIBERTY INSURANC		-	
INIO		Y #25-01 NORTH TOWER SINGAPORE	Ref:	CS/LIP24070435/Eqh3m4
	048583	1 #25-01 NORTH TOWER SINGAPORE	Date:	13/09/2024
			Code:	LIP
1.	•			
	Insured Veh.	YP 77Z	Veh. Inspected	FBU 1496L
	Policy No.	-	Coverage	0
	Claim No.	BVS24/0505	Excess	\$0.00
	Assign From	ANDY SEAH	Assign Date	26/07/2024
2. Vehicle Details				
	Make & Model	YAMAHA NMAX	C.C	155
	Engine No.	G3L8E1161581	Year of Reg.	26/08/2022
	Chassis No.	MH3SG5680NK139527	Colour	BLACK
	Odometer	3256 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	FAIR
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
3.		Conditions	o or ryres	
3.		Size	Make	Balance (mm)
3.	R/H Front Tyre	1	<u> </u>	Balance (mm)
3.	R/H Front Tyre L/H Front Tyre	Size	Make	
3.	-	Size	Make	
3.	L/H Front Tyre	Size 110/70-13	Make PIRELLI	5
4.	L/H Front Tyre R/H Rear Tyre	Size 110/70-13	Make PIRELLI PIRELLI	5
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	Size 110/70-13 130/70-13	Make PIRELLI PIRELLI of Damages	5
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINE	Size 110/70-13 130/70-13 Description of	Make PIRELLI PIRELLI of Damages	5
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	Size 110/70-13 130/70-13 Description of	Make PIRELLI PIRELLI of Damages RTION AND N/S BO	5
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINE	Size 110/70-13 130/70-13 Description of Discription of Discript	Make PIRELLI PIRELLI of Damages RTION AND N/S BO	5
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINE	Size 110/70-13 130/70-13 Description of DAMAGES AT THE FRONT, REAR PO	Make PIRELLI PIRELLI of Damages RTION AND N/S BO formation Inspection Date	5 5 DY.
4. THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINE IAGES SEE DETAILS. Accident Date	Size 110/70-13 130/70-13 Description of Discription of Discript	Make PIRELLI PIRELLI of Damages RTION AND N/S BO formation Inspection Date PER SERANGOON R	5 5 DY.
4. THE DAM 5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINE AGES SEE DETAILS. Accident Date Survey held at HE INSPECTION WAS	Size 110/70-13 130/70-13 Description of Discription of Discript	Make PIRELLI PIRELLI PIRELLI of Damages RTION AND N/S BO formation Inspection Date PER SERANGOON F arks DICE" BASIS.	5 5 DY. 29/07/2024 RD SINGAPORE 534561
4. THE DAM 5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINE AGES SEE DETAILS. Accident Date Survey held at HE INSPECTION WAS	Size 110/70-13 130/70-13 Description of Discription of Discript	Make PIRELLI PIRELLI PIRELLI Of Damages RTION AND N/S BO Formation Inspection Date PER SERANGOON FOR SERANGOON	5 DY. 29/07/2024 RD SINGAPORE 534561
4. THE DAM 5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINE AGES SEE DETAILS. Accident Date Survey held at HE INSPECTION WAS	Size 110/70-13 130/70-13 Description of Discription of Discript	Make PIRELLI PIRELLI PIRELLI Of Damages RTION AND N/S BO Formation Inspection Date PER SERANGOON FOR SERANGOON	5 DY. 29/07/2024 RD SINGAPORE 534561