

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To In Vehicle No: _____

at Workshop _____

of _____

Insured: _____

Policy No: _____

Claim's No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD1994A Yr Regn: 2016 / Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E250 C.D. 1991

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 214025 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120362B262162

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R: 245/40R18

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

D.O.I. 21/08/24

Survey held at HS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Check</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation: _____

3 + RS \$

Photos

Others

Report Format:

Report Form / P.P. / C