

## ASSIGNMENT

27/09/2021

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or NoLump Sum: PIP % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHC 8481 G Yr Regn: 28/07/2023

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prous CC: 1797Colour: Blue A/C: Insured / Std / NI / NASp. Reading: N.A T/Radio: Insured / Std / NI / NAEng/No: 2ZR2X01862C/No: 5TDAE3AU403001451

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60 217

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokohama

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 25/07/2024 D.O.I. 29/07/2024Survey held at 95rust nyen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	UOI SJK 8220 C
04/11/24	pinpin PIP 13,738.91 with 9 days of repair (Red. \$ 24288.51, 63%)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Other

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / LB.I: (\$ \_\_\_\_\_)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of First Submission	26/07/2024 09:14 (SGT)
Reported by	Actual Driver
Date of Accident	25/07/2024 20:30 (SGT)
Exact Location of Accident	KJE, Singapore
Additional Location Information	TOWARDS CHOACHU KANG
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8481G
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-97497426
Alternative Phone No	(Office) +65-65508768

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-24101861MFCT

### DRIVER

Name of Driver	LEE KWANG MENG
NRIC No	SXXXX497B
Date Of Birth	14/10/1967
Occupation	Outdoor

Driving Pass Date	23/05/1989
Driving experience	35 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97497426
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 875 WOODLANDS STREET 82#11-548
Address complement	-
Postcode	730875
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	UNKNOWN
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

ON THE DATE 25/07/2024 AT ABOUT 2030HRS WHILE I WAS DRIVING VEHICLE A BEARING REGISTRATION NUMBER SHC8481G ON THE WAY TO DROP OFF MY PASSENGER EN-ROUTE FROM NEX SHOPPING MALL TOWARDS 535 CHOA CHU KANG STREET 51 WHILE TRAVELLING ALONG THE SLIP ROAD OF KJE TOWARDS CHOA CHUBKANG ON LANE 1 SUDDENLY ALL THE VEHICLES INFRONT APPLIED BRAKES AND STOPPED STATIONARY UPON NOTICING THIS I ALSO APPLIED THE BRAKES ON VEHICLE A BUT WHILE DOING SO I GOT A JERK FROM BEHIND IT WAS VEHICLE B BEARING REGISTRATION NUMBER SJK8820C WHICH DID NOT MANAGE TO STOP ON TIME AND REAR ENDED VEHICLE A CAUSING DAMAGES TO VEHICLE A. THE DRIVER OF VEHICLE A IS HAVING NECK PAIN BACK PAIN AND WILL CONSULT DOCTOR SOON.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK8220C
Vehicle Manufacturer	Kia
Vehicle Model	CERATO 1.6(A) EX
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LIM YONG PENG,ALOYSIUS
NRIC No	SXXXX048J
Contact Number	-
Address	APT BLK 134 RIVERVALE STREET # 06-722
Address complement	-
Postcode	540134
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

# INJURED PERSONS DETAILS

## INJURED 1

Name of injured person	LEE WANG MENG
Gender	Male
Phone No	(Phone) +65-97497426
Address	BLK 875 WOODLANDS STREET 82#11-548
Address Complement	-
Post Code	730875
Approximate Age Years Old	56
Injuries Sustained	NECK AND BACK PAIN
Injured person in which vehicle?	SHC8481G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
  - (ii) investigating the accident and/or my claims.
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



Describe Circumstances of the Accident

ON THE DATE 25/07/2024 AT ABOUT 2030HRS WHILE I WAS DRIVING VEHICLE A BEARING REGISTRATION NUMBER SHC8481G ON THE WAY TO DROP OFF MY PASSENGER EN-ROUTE FROM NEX SHOPPING MALL TOWARDS 535 CHOA CHU KANG STREET 51 WHILE TRAVELLING ALONG THE SLIP ROAD OF KJE TOWARDS CHOA CHUBKANG ON LANE 1 SUDDENLY ALL THE VEHICLES INFRONT APPLIED BRAKES AND STOPPED STATIONARY UPON NOTICING THIS I ALSO APPLIED THE BRAKES ON VEHICLE A BUT WHILE DOING SO I GOT A JERK FROM BEHIND IT WAS VEHICLE B BEARING REGISTRATION NUMBER SJK8820C WHICH DID NOT MANAGE TO STOP ON TIME AND REAR ENDED VEHICLE A CAUSING DAMAGES TO VEHICLE A. THE DRIVER OF VEHICLE A IS HAVING NECK PAIN BACK PAIN AND WILL CONSULT DOCTOR SOON.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	821R

### Vehicle Details

Vehicle No.:	SHC8481G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Jul 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI HATCHBACK(AT)(2WD)
Primary Colour:	Blue
Manufacturing Year:	2023
Engine No.:	2ZR2X01862
Chassis No.:	JTDAE3AU403001451
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$28,006.00
Original Registration Date:	28 Sep 2023
First Registration Date:	28 Sep 2023
Transfer Count:	0
Actual ARF Paid:	\$8,709.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2031
PARF Rebate Amount:	\$6,531.00

### Intended COE Rebate Details

COE Expiry Date:	27 Sep 2031
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	8
PQP Paid:	\$78,122.00
COE Rebate Amount:	\$62,497.00
<b>Total Rebate Amount:</b>	<b>\$69,028.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Jul 2024

OK

## BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 26-Jul-24

INSURANCE: VOIMODEL: TOYOTA PRIUS (NEW)VEHICLE NO.: SHC 8481 G

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>Bnc</i> 2280.10	1	\$ 2,515.30	\$2,515.30
REAR TRUNK LID LOCK <i>Dem</i> 133.00	1	\$ 684.90	\$684.90
REAR TRUNK LID TOP TRIM <i>HN</i>	1	\$ 268.00	\$ 268.00
REAR TRUNK LID SIDE TRIM <i>HN</i>	2	\$ 161.30	\$ 161.30
REAR TRUNK LID COVER TRIM BOARD <i>HN</i>	1	\$ 655.30	\$655.30
REAR TRUNK LID RUBBER <i>deformed</i>	1	\$ 483.40	\$483.40
REAR TRUNK LID OUTER GARNISH <i>HS</i>	1	\$ 1,529.20	\$1,529.20
REAR TRUNK LID OUTER GARNISH SIDE COVER <i>HS</i>	2	\$ 78.70	\$157.40
REAR WINDSCREEN MOULDING <i>HN</i>	1	\$81.50	\$81.50
REAR TRUNK LID LOGO (PRIUS) <i>Hec</i>	1	\$ 85.82	\$85.82
REAR TRUNK LID LOGO (HEV) <i>Hec</i>	1	\$ 101.00	\$101.00
REAR TRUNK LID LOGO (TOYOTA STAR) <i>Hec</i>	1	\$ 74.67	\$74.67
THIRD BRAKE LIGHT <i>broken</i> 886.60	1	\$ 989.70	\$989.70
REAR TRUNK LID HINGE (LH/RH) <i>HN</i>	2	\$ 177.80	\$355.60
REAR TRUNK LID ABSORBER (LH/RH) <i>HN</i>	2	\$ 478.30	\$956.60
REAR TRUNK LID ABSORBER BRACKET (LH/RH) <i>HN</i>	2	\$ 478.30	\$956.60
REAR NO. PLATE LAMP <i>broken &amp; distorted</i>	2	\$ 94.70	\$189.40
REAR BUMPER <i>Deval</i> 595.10	1	\$ 855.60	\$855.60
REAR BUMPER RE-INFORCEMENT <i>Deval</i>	1	\$ 549.99	\$549.99
REAR BUMPER LOWER GARNISH <i>Deval</i> 511.10	1	\$ 741.70	\$741.70
REAR BUMPER SIDE RETAINER <i>HN</i>	2	\$ 192.10	\$384.20
REAR BUMPER UNDER CENTRE COVER <i>deformed</i>	1	\$ 391.20	\$391.20
REAR BUMPER TOWING COVER <i>SN</i>	1	\$ 19.70	\$19.70
REAR BUMPER CLIPS <i>Hec</i>	1	\$ 40.00	\$40.00



REAR BUMPER SIDE GARNISH HH	2	\$ 116.73	\$233.46	X
REAR BUMPER BRACKET HH	2	\$ 113.20	\$226.40	X
REAR BUMPER UNDER SIDE COVER HH	2	\$ 324.80	\$649.60	X 220/- SN
REAR BUMPER REVERSE SENSOR Dam 2pc 2panel	4	\$ 494.20	\$1,976.80	✓
REAR BUMPER REVERSE SENSOR WIRE HH	1	\$ 424.60	\$424.60	X
REAR BUMPER REFLECTOR (LH/RH) o/s HH n/s grade	2	\$ 258.80	\$517.60	✓
SMART KEY ANTENNA SENSOR HH	1	\$ 310.60	\$310.60	X
TAIL LAMP ASSY o/s HH n/s broken	2	\$ 1,129.20	\$2,258.40	✓
TAIL LAMP ASSY SIDE COVER HH	2	\$ 80.10	\$160.20	X
TAIL LAMP PANEL HH	2	\$ 574.50	\$1,149.00	X
REAR END PANEL Bw 912.00	1	\$ 1,008.40	\$1,008.40	✓
REAR END PANEL GARNISH broken / damaged	1	\$ 346.20	\$346.20	✓
REAR SPARE TYRE PANEL Dmbl	1	\$ 1,538.30	\$1,538.30	✓
REAR SPARE TYRE TOP COVER HH	1	\$ 617.10	\$617.10	X
REAR SPARE TYRE TOOL TRAY damaged 716.80	24	\$ 358.40	\$358.40	✓
SPARE TYRE LOCK NUT HH	1	\$ 123.76	\$123.76	X
REAR EXHAUST SILENCER BOX Dmbl / bt 1994.20	1	\$ 2,199.60	\$2,199.60	✓
REAR EXHAUST HEST SHIELD bt	1	\$ 223.20	\$223.20	✓
REAR EXHAUST PIPE HANGER SW	2	\$ 68.10	\$136.20	X
REAR FENDER, LH reg	1	\$ 1,855.70	\$1,855.70	X
REAR FENDER SHIELD (LH/RH) HH	2	\$ 387.80	\$775.60	X 623.80
REAR FENDER TRIMBOARD (LH/RH) torn 811.90 x2	2	\$ 1,323.34	\$2,646.68	X ✓
REAR FENDER AIR DUCT HH	2	\$ 115.00	\$230.00	X
REAR BLIND SPORT MONITOR HH	2	\$ 2,872.70	\$5,745.40	X
SUB TOTAL 15,063.88			\$38,939.28	
LESS 20% + 5% 11,297.91			\$7,787.86	
DISCOUNTED TOTAL			\$31,151.42	
REAR WINDSCREEN SEALANT Hw SN	1	\$46.00	\$46.00	✓
REAR NO. PLATE WITH TRIM COVER broken / bt SN	1	\$ 140.00	\$140.00	45/-
REAR TRUNK LID APPS STICKER Hw SN	1	\$ 56.00	\$56.00	✓
REAR TRUNK LID COMFORT & TEL NO. STICKER Hw SN	1	\$ 84.00	\$84.00	✓
REVERSE CAMERA HH SN	1	\$ 540.00	\$540.00	X

<b>SUB TOTAL</b>	221.00 451.00		<b>\$866.00</b>
<b>Labour Charge</b>			
Panel Beating	1	\$ 2,400.00	\$2,400.00
Spray Painting Charge	1	\$ 1,800.00	\$1,800.00
Wiring Charge	1	\$ 100.00	\$100.00
Tuff Kote	1	\$ 100.00	\$100.00
Towing Charge	1	\$ 80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear	1	\$ 150.00	\$150.00
Remove/Refix Rear Windscreen Glass	1	\$ 120.00	\$120.00
Remove/Refix Fuel Tank	1	\$ 80.00	\$80.00
Remove/Refix Exhaust Pipe	1	\$ 80.00	\$80.00
DIAGNOSTIC & Resetting ADAS OPTICAL SENSOR	1	\$ 550.00	\$550.00
Diagnostic & Resetting To Erase Fault Code	1	\$ 550.00	\$550.00
<b>TOTAL LABOUR</b>	1990.00		<b>\$6,010.00</b>
<b>ESTIMATE TOTAL</b>			<b>\$38,027.42</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

900/-  
800/-  
30/-  
40/-  
42/-  
80/-  
80/-  
42/-  
60/-  
42/-  
42/-

29/07/2024 @ 1630hrs

7/2 13,738.91

N/A Admin

P/Pat 9 days.

LKK Auto

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: