

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	le Des Experts En	Automobile
MS	MS FIRST CAPITAL		Ref:	CS/FCI24070452/Unp3
	16 RAFFLES QUAY	,	Date:	02/08/2024
	#42-01 HONG LEO SINGAPORE 04858			FCI2
	SINGAPORE 04000		Code:	
1.	In a come of Mark	Policy Particulars :- 1		
	Insured Veh.	SHB 6333U	Veh. Inspected	GBL 4123R
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24006556MFCT	Excess	\$0.00
	Assign From	BETTY	Assign Date	29/07/2024
2. Vehicle Details				
	Make & Model	NISSAN NV350 CARAVAN DX (A)	C.C	1998
	Engine No.	QR20013927R	Year of Reg.	05/07/2021
	Chassis No.	VR2E26132404	Colour	WHITE
	Odometer	56789 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
		0.20		<u> </u>
	R/H Front Tyre	195R15	BRIDGESTONE	6
	R/H Front Tyre L/H Front Tyre		BRIDGESTONE BRIDGESTONE	6
		195R15		
	L/H Front Tyre	195R15 195R15	BRIDGESTONE	6
4.	L/H Front Tyre R/H Rear Tyre	195R15 195R15 195R15	BRIDGESTONE BRIDGESTONE BRIDGESTONE	6 6
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195R15 195R15 195R15 195R15	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195R15 195R15 195R15 195R15 195R15  Description of the properties	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	195R15 195R15 195R15 195R15 195R15  Description of the properties	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages ORTION.	6 6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	195R15 195R15 195R15 195R15 195R15 Description ED DAMAGES AT THE FRONT N/S PC	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages ORTION.	6 6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN MAGES SEE DETAIL	195R15 195R15 195R15 195R15 195R15 Description of ED DAMAGES AT THE FRONT N/S PC S. General In	BRIDGESTONE BRIDGESTONE BRIDGESTONE of Damages DRTION.	6 6 6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN AGES SEE DETAIL  Accident Date	195R15 195R15 195R15 195R15 195R15 Description of ED DAMAGES AT THE FRONT N/S PC S. General In 25/07/2024 T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY	BRIDGESTONE BRIDGESTONE BRIDGESTONE Of Damages ORTION.  formation Inspection Date	6 6 6

**Estimate Days of Repair**