



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070456/Unp3
(BUDGET DIRECT INSURANCE)	Date:	30/08/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 2709D	Veh. Inspected	SMR 4081R
Policy No.	-	Coverage	0
Claim No.	C10030803/KR	Excess	\$0.00
Assign From	KAVIDHA RAJAN	Assign Date	29/07/2024

### 2. Vehicle Details

Make & Model	HONDA CIVIC 1.6 VTI CVT	C.C	1597
Engine No.	R16B25511470	Year of Reg.	02/01/2020
Chassis No.	MRHFC5650KT001272	Colour	BLACK
Odometer	80741 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40 ZR18	PIRELLI	6
L/H Front Tyre	225/40 ZR18	PIRELLI	6
R/H Rear Tyre	225/40 ZR18	PIRELLI	6
L/H Rear Tyre	225/40 ZR18	PIRELLI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	29/07/2024	Inspection Date	30/07/2024
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY@KAKI BUKIT, SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days