

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583		Ref:	CS/LIP24070465/Kvh3e2	
			Date:	19/08/2024	
	511 1 6711	0	Code:	LIP	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJT 2872M	Veh. Inspected	SMJ 2099X	
	Policy No.	-	Coverage	0	
	Claim No.	IVS24/1455	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	29/07/2024	
2.	2. Vehicle Details				
	Make & Model	HONDA GRACE (A)	C.C	1496	
	Engine No.	LEB6446651	Year of Reg.	26/02/2019	
	Chassis No.	GM41206627	Colour	METALLIC GREY	
	Odometer	150599 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: STANDARD ALLOY RIM	•		
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	185/60R15	GOODYEAR	8	
	L/H Front Tyre	185/60R15	GOODYEAR	8	
	R/H Rear Tyre	185/60R15	GOODYEAR	8	
	L/H Rear Tyre	185/60R15	GOODYEAR	8	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	26/07/2024	Inspection Date	30/07/2024	
	Survey held at	KIEN CHEONG MOTOR WORKS BLK 9 SIN MING IND EST SECTOR C #01-26 SINGAPORE 575644			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
FORMATED NORMAL DEDICE FOR DEDAID C Working David					

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days