

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W _____ m/s

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMF3169S Yr Regn: 2018, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Outlander C.D. 1998

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 51422 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GF7W0600178

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R: 225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Roadstone

Front _____ Rear _____

R/Bal. ob mm R/Bal. ob mm

L/Bal. ob mm L/Bal. ob mm

D.O.A. _____ D.O.I. 30/07/24

Survey held at JL Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

TP INC

COE Expiry: _____

Estimate given during: Yes ✓
1st Survey No ()

MV: _____

PV: _____

Nett: _____

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + R.S. \$ _____

Photos _____

Others _____

Report Format: _____

Report Form: _____