

CS/INC24070475/Aqh3

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin: \_\_\_\_\_  
 OD / TP RES / OD RES / EVA / INV / MV  
 To in: \_\_\_\_\_ Vehicle NO: \_\_\_\_\_  
 at W: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy: \_\_\_\_\_  
 Claims: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Vehicle: \_\_\_\_\_

Veh No: 5M0222SL Yr Regn: 2019, Sept  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Vellore C.D. 2494  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: 163191 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTX GF3DH 208 020715  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil S/Rim / STD A/Rim or  
 Tyre Size: F: 235/50R18  
 R: 235/50R18

(Policy Condition)  
 Remark: The vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>05/08/24</u>

Survey held at M6 solution  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear N/S.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP INC</u>
	<u>LS \$1700, 3 days (Red \$5040.70, 75%)</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ( )</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to? \_\_\_\_\_  
 1) 27/01 Typist \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 3  
 Resurvey No. of Trip: 2

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 \$ + RS. \$1  
 Photos  
 Others

Add Fee: \_\_\_\_\_  
 Site Insp (\$)  
 Interview (\$)  
 Tech. Inver (\$)

Report Forward: TP  
 E. from 24h / 12h / 1h