

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No.

19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	INCOME INSURANCE LTD		Ref:	CS/INC24060079/Tvh3e2
	75 BRAS BASAH R		Date:	02/10/2024
	INCOME CENTRE	SINGAPORE 189557	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SLN 6509U	Veh. Inspected	SLU 8868H
	Policy No.	-	Coverage	0
	Claim No.	MT/1281370-002	Excess	\$0.00
	Assign From	RODERIC YUEN	Assign Date	13/06/2024
2.				
	Make & Model	B.M.W. 318I	C.C	1499
	Engine No.	37775095B38B15A	Year of Reg.	28/12/2017
	Chassis No.	WBA8E36030NU82301	Colour	BLACK
	Odometer	82217 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.	3. Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	225/45 R18	PIRELLI	6
	L/H Front Tyre	225/45 R18	PIRELLI	6
	R/H Rear Tyre	225/45 R18	PIRELLI	6
	L/H Rear Tyre	225/45 R18	PIRELLI	6
4.	Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	11/06/2024	Inspection Date	13/06/2024 (11:40)
	Survey held at	vey held at JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days