

ASSIGNMENT

From: _____ Date: _____
 Estn: Estimate
 OD / TP RES / OD RES / EVA / INV / MV
 To In: Vehicle No: _____
 at W/O 10/10/15
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

N/S	O/S

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNM3744H Yr Regn: 2023 Sept.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienta Hybrid 1490
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 58938 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MXPL101038451

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15
 R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or Tourador

Front 06 mm Rear 06 mm
 R/Bal. 06 mm L/Bal. 06 mm
 D.O.A. 31/07/24

Survey held at MCR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP SCDF</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV : Yes (✓)</u>
	<u>PV : No (✓)</u>
	<u>Nett:</u>

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

1) ☐ : Preli. Report

2) ☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

Survey Fee:

Transportation:

3 + RS \$1

Photos

Others