

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts Eli Automobile					
MS	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI24070490/Dnp3	
	16 RAFFLES QUA		Date:	22/08/2024	
	#42-01 HONG LEONG BUILDING SINGAPORE 048581		Code:	FCI2	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 6096Z	Veh. Inspected	GBG 4641M	
	Policy No.	D-24102085MFVS/24	Coverage	0	
	Claim No.	D24006611MFVS	Excess	\$0.00	
	Assign From	JOANNE	Assign Date	30/07/2024	
2.	2. Vehicle Details				
	Make & Model	NISSAN NV200	C.C	1461	
	Engine No.	K9KC400D056655	Year of Reg.	17/08/2017	
	Chassis No.	VSKYBAM20Z0143292	Colour	RED	
	Odometer	214328 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	175/70 R14	GITI	5	
	L/H Front Tyre	175/70 R14	GITI	5	
	R/H Rear Tyre	175/70 R14	GITI	5	
	L/H Rear Tyre	175/70 R14	GITI	5	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	26/07/2024	Inspection Date	30/07/2024	
	Survey held at	ALFRED AUTO SERVICES & SUPPLIES - 5035 ANG MO KIO AVE 3 #01-351 INDUSTRIAL PARK 2 SINGAPORE 569538			
5a. Remarks					
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days