



Your Ref: SS/10427/SOMPO/SUZANNA

Date: 25th September 2024

Our Ref: CS1/LAW24070496/Dnp3

M/s Sompo Insurance Singapore PL

C/o Alan Shankar & Lim LLC

151 Chin Swee Road

#09-16 Manhattan House

Singapore 169876

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMH 523L

INSURED VEHICLE: SJQ 581G

ACCIDENT DATE: 11/02/2023

We thank you for your instruction on 29/07/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMH 523L from M/s Precise Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SMH 523L and SJQ 581G.
- c) Colour damaged vehicle photographs of SMH 523L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMH 523L
Make & Model	: BMW X2 Sdrive18i mspt led fog lights
Year of Registration	: 2018
Chassis Number	: WBAYH12010EM92858
Engine Capacity	: 1499 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.