

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ NO1 24072501/Unp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBJ 6092Tat Workshop m/s Erntreeof SLV1329M

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$15500

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBJ 6092T Yr Regn: 13/09/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Vaniche T max 500 c.c. 499Colour: Mercon A/C: Insured / Std / NI / NASp. Reading: 135581 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JVASJ061000047319Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120 / 70 - 15R: 160 / 60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 26/07/24 D.O.I. 31/7/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S, N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/10/24	Check b.k. fall on left, accident scene photo at folder coe unrel 31-07-2030 ATA \$2611 B-1 6yr. 1/s \$2800 insured AM (con. (Red. \$5579, 66%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format : _____

Lump Sum / I.B.I.: (\$)

Survey Fee:

Transportation:

TOTAL

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	730Z
Vehicle Details	
Vehicle No.:	FBJ6092T
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2024
Vehicle Make:	YAMAHA
Vehicle Model:	TMAX 500
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	J406E068191
Chassis No.:	JYASJ061000047319
Maximum Power Output:	-
Open Market Value:	\$9,923.00
Original Registration Date:	13 Sep 2010
First Registration Date:	13 Sep 2010
Transfer Count:	4
Actual ARF Paid:	\$1,489.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2030
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$4,352.00
COE Rebate Amount:	\$2,611.00
Total Rebate Amount:	\$2,611.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 31 Jul 2024

OK

Advertisement



Motorcycles > Motorcycles for Sale > Class 2



Register

Login

Search for an item



Yamaha tmax 500

S\$15,000

Used

Meetup

Simei

Description

Bumped
3 weeks agoMake
YamahaType
Scooter

Coe 2029

Renewable

Cash and carry!

Or swap with xmax ,coe must be 4yrs and above

Meet-up

Simei



irfan zainal @irfan.zainal28

5.0 ★★★★★ (2 reviews)

Chat

Sign in to make offer

S\$ 15000

Make Offer

Returns and refunds

Depends on the seller's decision. Not covered by Buyer Protection.

Safety policy

Pay only at the meet-up. Transferring money directly to strangers puts you at risk of e-commerce scams.

Advertisement

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 30-Jul-24

Estimate no.

1427

Plate No. FBJ6092T

Model. T-MAX500

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	REAR RIM	\$ 850.00	q	
2	REAR RIM BEARING X2	\$ 280.00	X	
3	REAR SWING ARM	\$ 900.00	X	
4	EXHAUST PIPE	\$ 1,850.00	✓	
5	EXHAUST BRACKET	\$ 380.00	✓	
6	EXHAUST COVER	\$ 350.00	X	
7	RAER FAIRING COVER R	\$ 380.00	X	
8	REAR FAIRING COVER L	\$ 380.00	✓	
9	MAINSTAND	\$ 280.00	X	
10	REAR FOOTREST L	\$ 180.00	X	
11	FRONT FOOTREST BOARD L	\$ 350.00	✓	
12	FRONT FOOTREST UNDER COVER L	\$ 300.00	✓	
13	FRONT FAIRING PANEL COVER L	\$ 320.00	✓	
14	FRONT FORK SET	\$ 800.00	X	
15	HANDLE BAR	\$ 350.00	X	
16	MIRROR SET	\$ 280.00	X	
17	SPRAY COVERSET	\$ 480.00	280	
18	LABOUR	\$ 600.00	300	

not authorized
me 62583561
unauthorized
31/7/24
2/5 #2800
3 days
Zhu phi. Am 11/7

9-3265
102
2928.50
580
3518.50
202
3714

\$ 9,310.00
Sub Total : \$ 8,379.00
GST 9% \$ 754.11
Total: \$ 9,133.11

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

LIK Auto Consultants hence notify
the Repairer of the following:
• To recovery before/after spray painting
• In display damaged parts
• Parts prices are subject to confirmation
• Third party survey is on a "Without Fault" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be made up to the
• To final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: