ASS. REC. BY: REF: C7Z/C	CS/CTI24070508/Kvp3e2
Kenneth	SSICNMENT
From: Date:	Veh No: SLX 8830 A Yr Regn: OF, 18
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or
To Inspect Vehicle No:	1 (A)
at Workshop m/s & M	100 E c.c 14P6
of 869	District No. Insured / Std / NI / NA
Insured: SJU 4961X	- Irkadio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No. CNIM24D204200	CNO: MR 23231= 3301118861
Complement	Gen. Cond: Good / Fair / Poor / Burnt
the same are seen as the same as	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / S/RIM / S/D A/RIM or
	Tyre Size: F: Dvn 185/60R15
(Policy Condition)	R: Falker
Remark: The veh had commenced Its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: \$55k	Front
IDAC Accident Rport: Consistent?: Yes or No	R/Bal Z
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 7 mm R/Bal. 9 mm
Est. Repairs: 4- days Res.: Yes or No	D.O.A. 78/7/194
Lum Sum: 20 % 3 Val.: Yes or No	0.0.1. 6/18/2024
	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	The state of the s
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
22/0	
13/8 6/ Sup 82800/2 Costor (re	ed 3484.48, 55%)
	the distance of the same of th
R	The second secon
	The second secon
	The second secon
Oato/Time, File Pass to? : Prell. Report	Ne Of Donals
i) : Final Report	ys Of Repair: 4
Oute/Fime, File Return to?	survey No. of Trip: Survey Fee:
Add Fee:	Transportativi
,	: Site Insp (\$ )_s-Rssi
Report Format:	: Interview (\$ ), Finds
Lump Sum / I.B.I: (S	Tech Invs (\$ ) Others
	Weekend (\$
	TOTAL

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	864Z
Vehicle No.:	SLX8830A
Vehicle to be Exported:	No
ntended Deregistration Date:	21 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2NR5211648
Chassis No.:	MR2B23F3301118861
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,707.00
Original Registration Date:	16 Apr 2018
First Registration Date:	16 Apr 2018
Fransfer Count:	0
Actual ARF Paid: ntended PARF Rebate Details	\$13,707.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Apr 2028
PARF Rebate Amount: Intended COE Rebate Details	\$8,909.00
COE Expiry Date:	15 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$13,511.00
otal Rebate Amount: Message	\$22,420.00
You will not be eligible for any COE rebate from the curr	rent COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 20 Aug 2024

SL0M247T000D / Lai Huat (Meng Kee) Motor Pte Ltd ENTRY DATE & TIME: 29/07/2024 16:33 (SGT) SUBMITTED BY: Jenny Lim VERSION: 1 (29/07/2024 16:33 (SGT))



## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of First Submission

Reported by

Date of Accident **Exact Location of Accident** 

Additional Location Information

Country/State of Loss

29/07/2024 16:33 (SGT)

Actual Driver

29/07/2024 09:10 (SGT)

Chin Swee Rd, Singapore

Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SLX8830A

### INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

**Email Address** 

Mobile Phone No

Alternative Phone No

Goh Shon Hai

S2538864Z

francisgoh@conren.com.sg

(Phone) +65-83394385

### VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

Toyota Vios

Private use

No - Claiming third party

Private car

Auto

1500

## INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Sompo Insurance Singapore Pte. Ltd. D24MTPV01004841

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

Accident report SL0M247T000D

Goh Gek Lin S1344512E 28/04/1959 Indoor

Page 1 of 12

Driving Pass Date Driving experience

Gender

Mobile Number Alt. Phone Number

Email Address Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

01/08/1979

44 YEARS AND 11 MONTHS

Female

(Phone) +65-83394385

francisgoh@conren.com.sg

47 Burgundy Drive

658841

No

Spouse

No

-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collision - Head to Rear

Clear Dry

No

No

Yes

2

No

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

Translator's name

Translator's ID

Translator's phone number

Translator's email

Original language used in the statement

PASSENGER 1

Name

Gender

Unknown

Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

No

No

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant

SJU4961X Hyundai

-



Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Yahya bin Kamseer
NRIC No	S1531981Z
Contact Number	-
Address	-
Address complement	_
Postcode	-
Insurance Company Name	_
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### SKETCH PLAN

### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Farm must be completed by the Policyhalder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance dompanies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

## 5. Any false reporting may be referred to the Traffic Police Department for investigation.

- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
  report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/taw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
   (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



uit Next scions. You	slow down a stopped. I follow (B) collided anto the rear	Mou
of my car	eh (B) collided anto the rear	
3P dain @	EM SOLUTION PTE LTU  160 Sin Ming Drive #03-18/19 Sin Ming Autocity Singapore 575722 Tel: 6456 0226 Fax: 6458 4500 Email: emautosolution@singaet.com	
	,	
eclaration Ve declare the foregoing particulars are true in Avery respec		
Gov M		\





# E M Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity Singapore 575722 Tel: 64560226

GST/Reg. No: 201016308K

Not Norhain My & 2800h Pulmy After Pains

**ESTIMATE** 

Date: 20th August 2024

Veh No: SLX 8830A Make/Model: Toyota Vios Chassis No: MR2B23F3301118861

5,874.83

Date of Acc: 29.07.24 TP Veh No: SJU 4961X

S/No	Qty Description		Unit	<b>Unit Price</b>			Amount		
		<u>Materials</u>				0			
1	1 pc	Rear Boot Lid			5	B	947.10		
2	1 pc	Rear Boot Lid Vios Emblem			5		68.60	_	
3	1 pc	Rear Boot Lid E Emblem			Ş	ne,	41.55		
4	1 pc	Rear Boot Lid Toyota Logo			5	1 Man			
5	1 pc	Rear Boot Lid Mechanism Lock			5		231.60	X	
6	1 pc	Rear Bumper			5	Bu	631.50		
7	2 pcs	Rear Bumper Reflector L/R	\$	121.60	5		243.20		
8	2 pcs	Rear Bumper Side Retainer L/R	\$	89.95	\$	slspir	179.90	4	
9	2 pcs	Rear Bumper Bracket L/R	\$	86.55	5	n	173.10	X	
10	1 pc	Rear End Panel			5	R	780.10	X	
11	1 pc	Rear End Panel Top Garnish		wy U	d	5	161.90		
12	1 pc	Rear Boot Weatherstrip	80.715N	3	5	RAIPI	161.42	501	
13	1 pc	Rear Spare Tire Tray			Ç		391.20		
					5	5 4	,079.77		
			Le	ess 25%	5	5 1	,019.94		
			Par	ts Total	: 5	5 3	,059.83		
		Special Nett						_	
1	1 set	Reverse Sensor			9	Del	250.00	100	
2	1 set	Rear Bumper Clips			5		45.00		
3	1 set	End Panel Top Garnish Clips			5	ne:	40.00		
			Spec	ial Nett	: 5	5	335.00	-8	
		Labour							
1	To remove	& rearrange electrical wirings, check lightings			Ç	5	80.00	151	
2	To remove	& replace upholstry, trim garnishes to facilitate repairs	i.		5		100.00		
3		transfer boot lid components			5		100.00	501	
4		repair & replace damaged bodyparts, realign bodywo	rk					-	
		consistent to the accident.			5	5 1	,000.00	90	
5		espray painting on affected portions.					,000.00	60	
6		& renew reverse sensor			9		100.00	301	
7	Rust proofi	ng on affected portions.			5		100.00	30	
1150	The second secon	LKK Auto Consultants hence no	Labor	ır Total	: - 5		,480.00	- 200	

Mr

**Goh Shon Hai** 

47 Burgundy Drive

Singapore 658841

for E M Solution Pte Ltd

the Repairer of the following: Total Parts & Labour: \$ To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

Tel: 64560226 GST/Reg. No: 201016308K

## Supplementary

Date: 21st August 2024

Veh No : SLX 8830A

Make/Model: Toyota Vios


Chassis No: MR2B23F3301118861

Date of Acc : 29.07.24

TP Veh No : SJU 4961X

h Shon Hai	
Burgundy Drive	
gapore 658841	

Qty	Description						
	Materials		Unit Price	Amount			
1 pc	Rear Bumper Reinforcement	221-20					
1 pc	Keyless Antenna	321-30	Br	\$ 360.70			
	- Trees Airceinia		cnz	\$ 185.50			
				\$ 546.20			
			Less 25%	\$ 136.55			
			Parts Total	\$ 409.65			
			DEMONSTRATION OF THE PARTY OF T				



for E M Solution Pte Ltd

ts quoted were based on visual inspection. Should additional parts be found damaged upon nantling, we will seek your approval before proceeding.