



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070513/Rnp3m4
(BUDGET DIRECT INSURANCE)	Date:	12/11/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMT 1501E	Veh. Inspected	SKS 752H
Policy No.	-	Coverage	0
Claim No.	C10030864/MC	Excess	\$0.00
Assign From	MONICA CHUNG	Assign Date	31/07/2024

### 2. Vehicle Details

Make & Model	BMW 116D 5DR	C.C	1496
Engine No.	37715151B37D15A	Year of Reg.	29/03/2018
Chassis No.	WBA1V720X05G87454	Colour	GREY
Odometer	109383 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/35 ZR19	MICHELIN	6
L/H Front Tyre	235/35 ZR19	MICHELIN	6
R/H Rear Tyre	235/35 ZR19	MICHELIN	6
L/H Rear Tyre	235/35 ZR19	MICHELIN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	28/07/2024	Inspection Date	07/08/2024
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days