

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No.

19-9607198-R Affiliated to Federation Internationale Des Experts En Automobile MS INCOME INSURANCE LTD Ref: CS/INC24080001/Agh3m4 75 BRAS BASAH ROAD Date: 24/10/2024 **INCOME CENTRE SINGAPORE 189557** Code: INC 1. **Policy Particulars :- THIRD PARTY CLAIM** Insured Veh. YP 5497L Veh. Inspected **SNJ 745R** Policy No. 0 Coverage Claim No. MT/1287576-002 **Excess** \$0.00 **Assign From AZHARI AFIDI Assign Date** 01/08/2024 2. **Vehicle Details** C.C Make & Model **KIA CARENS** 1685 DF4DGH218487 Engine No. Year of Reg. 06/04/2018 Chassis No. KNAHU815VJ7199072 Colour **BRONZE** Odometer 98069 KM IN ORDER Steering **Brakes** IN ORDER GOOD General Modification(s) RIMS: SPORTS RIM **Conditions of Tyres** 3. Size Make Balance (mm) 215/45R17 **ROADSTONE R/H Front Tyre** 6 L/H Front Tyre 215/45R17 **ROADSTONE** 6 6 R/H Rear Tyre 215/45R17 **ROADSTONE ROADSTONE** 6 L/H Rear Tyre 215/45R17 **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5.	5. General Information		
	Accident Date	23/07/2024	Inspection Date 01/08/2024 (12:08)
	Survey held at	vey held at JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days